

Inspection Photos

API: 061-06838

Operator: INVESTMENT EQUIPMENT LLC

Inspection Date: 5/8/2024



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos



Photo 1. Facing southeast toward the location.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

API: 061-06838 | Date: 5/8/2024

Inspection Photos



Photo 2. There is a pile of oily gravel material stored on location that must be removed and properly disposed.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

API: 061-06838 | Date: 5/8/2024

Inspection Photos



Photo 3. Facing toward the wellsite. The chemical container has tipped over.



Inspection Photos



Photo 4. The chemical container at the backside has also tipped over.



Inspection Photos



Photo 5. There is a conex at the east side of the location which must be removed. Erosion has occurred underneath the conex. The soils need to be stabilized once conex has been removed..



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

API: 061-06838 | Date: 5/8/2024

Inspection Photos



Photo 6. Facing toward the tank battery. The H₂S wind sock is missing.



Inspection Photos



Photo 7. There are stained soils at the back side of the tank battery that must be cleaned up.

