

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

05/01/2024

Submitted Date:

05/10/2024

Document Number:

707800941

FIELD INSPECTION FORM

Loc ID: 447512
Inspector Name: Ramsey, Scott
On-Site Inspection:
2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 10805
Name of Operator: FULCRUM ENERGY OPERATING LLC
Address: 240 SAINT PAUL STREET SUITE 502
City: DENVER State: CO Zip: 80206

Findings:

- 13 Number of Comments
- 4 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Penner, annalee		annalee@fulcrumef.com	
, Fulcrum		inspections@fulcrumeo.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
447510	WELL	AP	08/22/2022	LO	057-06577	Hebron 0780 8-18H	AP
447511	WELL	AP	08/22/2022	LO	057-06578	Hebron 0780 10-18H	AP
447513	WELL	AP	08/22/2022	LO	057-06579	Hebron 0780 9-18H	AP
447514	WELL	AP	08/22/2022	LO	057-06580	Hebron 0780 6-18H	AP
447586	WELL	PR	01/01/2024	OW	057-06581	Peters 0781 15-13H12	PR
447587	WELL	PR	01/01/2024	OW	057-06582	Peters 0781 13-13H12	PR
447589	WELL	PR	12/01/2023	OW	057-06583	Peters 0781 11-13H12	PR
447590	WELL	PR	12/01/2022	OW	057-06584	Peters 0781 9-13H12	PR
448966	WELL	PR	12/01/2023	OW	057-06590	Peters 0781 10-13H12	PR

General Comment:

[ECMC Inspection Report Summary](#)
On Wednesday 5/1/2024, I, Inspector Scott Ramsey, conducted a routine inspection at Open Range 18 pad, at Location # 447512 in Jackson county Colorado.
Any Corrective Actions from previous Inspections that have not been addressed are still applicable.
While there, I observed normal operations. This location is within or in close proximity to a CPW Density/High Priority Habitat, black bear, NSO habitat, Wildlife black bear Management and Density habitat.
During this inspection the following possible compliance issues were observed:
1. Random debris
2. Random staining
3. Lack of battery signage
4. Some areas show lack of stabilization/compaction

Refer to photograph of observed compliance issue.
A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.
This is a summary of inspection report.

Location

Overall Good:

Signs/Marker:

Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:	Lack of battery signage		
Corrective Action:	Provide proper signage	Date:	06/27/2024

Emergency Contact Number:

Comment:	911/970-594-0477	Date:	
Corrective Action:		Date:	

Good Housekeeping:

Type	DEBRIS		
Comment:	Random debris		
Corrective Action:	Remove debris	Date:	05/27/2024
Type	OTHER		
Comment:	Random staining		
Corrective Action:	Remove stained material, dispose of properly and securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition.	Date:	05/27/2024

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:

Type			corrective date
Type: Pump Jack	# 5		
Comment:			
Corrective Action:		Date:	
Type: Other	# 5		
Comment:	Well heads		
Corrective Action:		Date:	
Type: Vertical Separator	# 5		
Comment:			
Corrective Action:		Date:	

Type: Bradenhead	# 5	
Comment:		
Corrective Action:		Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	1	400 BBLs	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth				
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO	
Comment:		
Corrective Action:	Date:	

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities									
Facility ID:	447510	Type:	WELL	API Number:	057-06577	Status:	AP	Insp. Status:	AP
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									
Facility ID:	447511	Type:	WELL	API Number:	057-06578	Status:	AP	Insp. Status:	AP
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									
Facility ID:	447513	Type:	WELL	API Number:	057-06579	Status:	AP	Insp. Status:	AP
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									
Facility ID:	447514	Type:	WELL	API Number:	057-06580	Status:	AP	Insp. Status:	AP
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									
Facility ID:	447586	Type:	WELL	API Number:	057-06581	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing								
Corrective Action:							Date:		
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									
Facility ID:	447587	Type:	WELL	API Number:	057-06582	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing								
Corrective Action:							Date:		
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									
Facility ID:	447589	Type:	WELL	API Number:	057-06583	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing								
Corrective Action:							Date:		
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									
Facility ID:	447590	Type:	WELL	API Number:	057-06584	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing								
Corrective Action:							Date:		
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									
Facility ID:	448966	Type:	WELL	API Number:	057-06590	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing								
Corrective Action:							Date:		
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Berms						
Compaction	Fail					Light compaction in areas

Comment: 1. Some areas show lack of stabilization/compaction
Places with sparse to no gravel & light compaction are present on location. Sparse to no gravel and light compaction could lead to future stabilization and tracking issues.

Corrective Action: Install, maintain or repair required BMPs

Date: 06/28/2024

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
707800945	Photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6543924