

Inspection Photos

Location Name: CAERUS PICEANCE LLC FEDERAL 30-15BB (PN30) Pad

Location #: 334060



Photo # 6450 From entrance to location



Photo # 6451 Location



Inspection Photos

Location Name: CAERUS PICEANCE LLC FEDERAL 30-15BB (PN30) Pad

Location #: 334060



Photo # 6452 Location



Photo # 6453 Location

Inspection Photos

Location Name: CAERUS PICEANCE LLC FEDERAL 30-15BB (PN30) Pad

Location #: 334060



Photo # 6454 Location



Photo # 6455 Location



Inspection Photos

Location Name: CAERUS PICEANCE LLC FEDERAL 30-15BB (PN30) Pad

Location #: 334060



Photo # 6456 Suspected tank leak/tank appears to lack integrity (Tank # 81735)



Photo # 6457 Suspected tank leak/tank appears to lack integrity (Tank # 81735)

Inspection Photos

Location Name: CAERUS PICEANCE LLC FEDERAL 30-15BB (PN30) Pad

Location #: 334060



Photo # 6458 Suspected tank leak/tank appears to lack integrity (Tank # 81735)



Photo # 6459 Stained gravel in secondary containment

Inspection Photos

Location Name: CAERUS PICEANCE LLC FEDERAL 30-15BB (PN30) Pad

Location #: 334060



Photo # 6460 Debris