

# Inspection Photos

Location Name: CAERUS PICEANCE LLC DAYBREAK FEDERAL 19-2 (PJ19) Pad

Location #: 417538



Photo # 6526 From entrance to location

Photo # 6527 Location

# Inspection Photos

Location Name: CAERUS PICEANCE LLC DAYBREAK FEDERAL 19-2 (PJ19) Pad

Location #: 417538



Photo # 6528 Location

Photo # 6529 Location

# Inspection Photos

Location Name: CAERUS PICEANCE LLC DAYBREAK FEDERAL 19-2 (PJ19) Pad

Location #: 417538




Photo # 6530 Location

Photo # 6531 Location

## Inspection Photos

Location Name: CAERUS PICEANCE LLC DAYBREAK FEDERAL 19-2 (PJ19) Pad

Location #: 417538



Photo # 6532 Location



Photo # 6533 Location

## Inspection Photos

Location Name: CAERUS PICEANCE LLC DAYBREAK FEDERAL 19-2 (PJ19) Pad

Location #: 417538



Photo # 6534 Location




Photo # 6535 Location

## Inspection Photos

Location Name: CAERUS PICEANCE LLC DAYBREAK FEDERAL 19-2 (PJ19) Pad

Location #: 417538



**Photo # 6536 Bird protection on ECD damaged & needs maintenance/wildlife hazard/available for entry by wildlife**



**Photo # 6537 Bird protection on ECD damaged & needs maintenance/wildlife hazard/available for entry by wildlife**

## Inspection Photos

Location Name: CAERUS PICEANCE LLC DAYBREAK FEDERAL 19-2 (PJ19) Pad

Location #: 417538



Photo # 6538 Tank containment damaged/buckling



Photo # 6539 Tank containment damaged/buckling

## Inspection Photos

Location Name: CAERUS PICEANCE LLC DAYBREAK FEDERAL 19-2 (PJ19) Pad

Location #: 417538



Photo # 6540 Debris