

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC Domestic Tap 34NENW

Location # 323790

Facility # 456910



Photo # 6604 Domestic tap



Photo # 6605 Domestic tap

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC Domestic Tap 34NENW

Location # 323790

Facility # 456910



Photo # 384 From inspection 708902565 conducted on 12/19/2023 PRV vent line lacks cap



Photo # 1909 From inspection 708902696 conducted on 01/04/2024 PRV vent line lacks cap

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC Domestic Tap 34NENW

Location # 323790

Facility # 456910



Photo # 6606 PRV vent line lacks cap/does not comply CECMC pressure safety device rules



Photo # 385 From inspection 708902565 conducted on 12/19/2023 PRV vent line lacks cap

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC Domestic Tap 34NENW

Location # 323790

Facility # 456910



Photo # 1910 From inspection 708902696 conducted on 01/04/2024 PRV vent line lacks cap



Photo # 6607 PRV vent line lacks cap/does not comply CECMC pressure safety device rules

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC Domestic Tap 34NENW

Location # 323790

Facility # 456910



**Photo # 6608 PRV vent line lacks cap/does not comply
CECMC pressure safety device rules**



**Photo # 6609 PRV vent line lacks cap/does not comply
CECMC pressure safety device rules**