

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:
05/07/2024
Submitted Date:
05/08/2024
Document Number:
715200201

FIELD INSPECTION FORM

Loc ID 321081 Inspector Name: Welsh, Brian On-Site Inspection 2A Doc Num: _____

Status Summary:
 THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Findings:
7 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

Operator Information:
ECMC Operator Number: 61650
Name of Operator: MURFIN DRILLING COMPANY INC
Address: 250 N WATER ST STE 300
City: WICHITA State: KS Zip: 67202

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Quint, Craig		craig.quint@state.co.us	
Goodrich, Cristina	(316) 858-8664	cgoodrich@murfininc.com	
Taylor, Chad		chad.taylor@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
205978	WELL	TA	06/22/2023	ERIW	009-06393	S E CAMPO UNIT 601W	TA

General Comment:
Routine UIC Inspection

Location				
Lease Road:				
	Type	Access		
	comment:	Gravel road through pasture		
	Corrective Action:		Date:	
Overall Good: <input checked="" type="checkbox"/>				
Signs/Marker:				
	Type	WELLHEAD		
	Comment:	Lease sign by wellhead		
	Corrective Action:		Date:	
Emergency Contact Number:				
	Comment:			
	Corrective Action:			
Date: _____				
Overall Good: <input checked="" type="checkbox"/>				
Spills:				
Type	Area	Volume		
In Containment: No				
	Comment:			
<input type="checkbox"/> Multiple Spills and Releases?				
Fencing/:				
	Type	OTHER		
	Comment:	Pipe fence around solar panels		
	Corrective Action:		Date:	
	Type	WELLHEAD		
	Comment:	Pipe fence around wellhead		
	Corrective Action:		Date:	
Equipment:				
				corrective date
Type:	Ancillary equipment	# 3		
	Comment:	Wellhead w/water meter, solar powered cathodic rectifier		
	Corrective Action:		Date:	
Venting:				
	Yes/No			
	Comment:			
	Corrective Action:		Date:	
Flaring:				
Type				
Comment:				
Corrective Action:		Date:		

Inspected Facilities

Facility ID: 205978 Type: WELL API Number: 009-06393 Status: TA Insp. Status: TA

Underground Injection Control

UIC Violation: _____ Maximum Injection Pressure: _____

UIC Routine

Inj./Tube:	Pressure or inches of Hg _____ (e.g. 30 psig or -30" Hg)	Previous Test Pressure _____	MPP _____
TC:	Pressure or inches of Hg _____	Previous Test Pressure _____	Inj Zone: <u>LSNGC</u>
Brhd:	Pressure or inches of Hg _____	Previous Test Pressure _____	Last MIT: <u>08/02/2021</u>
			AnnMTReq: _____

Comment: UIC MIT was performed on 8/3/21. Field is SI at tank battery. Wellhead and flowline have been LOTO by operator

Form 5B (403406061) has been approved. Form 6A (403579639) has been approved with a plug date of 12/31/28

Continue with bradenhead monitoring and testing in accordance with rule 419.b.

Corrective Action: _____ Date: _____

Method of Injection: _____

Test Type: _____ Tbg psi: _____ Csg psi: _____ BH psi: _____

Insp. Status: _____

Comment: _____

Corrective Action: _____ Date: _____

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
715200219	location photo	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6545197