

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

05/10/2024

Submitted Date:

05/13/2024

Document Number:

693807294

FIELD INSPECTION FORM

Loc ID: 314535 Inspector Name: BROWNING, CHUCK On-Site Inspection: 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 10779
Name of Operator: SCOUT ENERGY MANAGEMENT LLC
Address: 13800 MONTFORT DRIVE SUITE 100
City: DALLAS State: TX Zip: 75240

Findings:

8 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Browning, Chuck	970-433-4139	chuck.browning@state.co.us	Field Inspector
Taylor, Chad	(720) 788-6197	chad.taylor@state.co.us	Underground Injection Lead
Sanford, Anita	970-640-3572	anita.sanford@scoutep.com	Regulatory Specialist
Labowskie, Steve		steve.labowskie@state.co.us	
Johnson, Mike	972-674-8679	Mike.Johnson@scoutep.com	Regional Manager

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
228959	WELL	IJ	11/01/2022	ERIW	103-06019	COLTHARP W H A-1	AC

General Comment:

Routine UIC inspection.

Location

Lease Road:			
	Type	Access	
	comment:		
	Corrective Action		Date:
	Type	Main	
	comment:		
	Corrective Action		Date:

Overall Good:

Signs/Marker:			
	Type	WELLHEAD	
	Comment:		
	Corrective Action:		Date:

Emergency Contact Number:			
	Comment:	970-675-3700	
	Corrective Action:		Date: _____

Overall Good:

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:			
	Type	WELLHEAD	
	Comment:	Chain link	
	Corrective Action:		Date:

Equipment:			corrective date
Type: Deadman # & Marked	# 4		
	Comment:		
	Corrective Action:		Date:
Type: Bradenhead	# 1		
	Comment:		
	Corrective Action:		Date:

Venting:			
	Yes/No	NO	
	Comment:		
	Corrective Action:		Date:

Flaring:			
Type			

Comment:	
Corrective Action:	Date:

Inspected Facilities

Facility ID: 228959 Type: WELL API Number: 103-06019 Status: IJ Insp. Status: AC

Underground Injection Control

UIC Violation: _____ Maximum Injection Pressure: _____

UIC Routine

Inj./Tube:	Pressure or inches of Hg <u>1950</u>	Previous Test Pressure _____	MPP _____
	(e.g. 30 psig or -30" Hg)		Inj Zone: <u>WEBR</u>
TC:	Pressure or inches of Hg <u>0</u>	Previous Test Pressure _____	Last MIT: <u>04/28/2022</u>
Brhd:	Pressure or inches of Hg <u>80</u>	Previous Test Pressure _____	AnnMTReq: _____

Comment: Routine UIC inspection. Active injection at time of inspection.

Corrective Action: _____ Date: _____

Method of Injection: PUMP FEED

Test Type: _____ Tbg psi: _____ Csg psi: _____ BH psi: _____

Insp. Status: _____

Comment: _____

Corrective Action: _____ Date: _____

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Berms	Pass	Gravel	Pass			

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
693807295	Inspection photos 5/10/2024	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6545857