

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/10/2024

Submitted Date:

05/13/2024

Document Number:

693807304

**FIELD INSPECTION FORM**Loc ID 314598 Inspector Name: BROWNING, CHUCK On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**

ECMC Operator Number: 10779

Name of Operator: SCOUT ENERGY MANAGEMENT LLC

Address: 13800 MONTFORT DRIVE SUITE 100

City: DALLAS State: TX Zip: 75240

**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

8 Number of Comments

0 Number of Corrective Actions

☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

| Contact Name     | Phone          | Email                       | Comment                    |
|------------------|----------------|-----------------------------|----------------------------|
| Browning, Chuck  | 970-433-4139   | chuck.browning@state.co.us  | Field Inspector            |
| Johnson, Mike    | 972-674-8679   | Mike.Johnson@scoutep.com    | Regional Manager           |
| Sanford, Anita   | 970-640-3572   | anita.sanford@scoutep.com   | Regulatory Specialist      |
| Taylor, Chad     | (720) 788-6197 | chad.taylor@state.co.us     | Underground Injection Lead |
| Labowskie, Steve |                | steve.labowskie@state.co.us |                            |

**Inspected Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num   | Facility Name      | Insp Status |
|-------------|------|--------|-------------|------------|-----------|--------------------|-------------|
| 229105      | WELL | IJ     | 09/01/2023  | ERIW       | 103-06187 | LARSON, M B C 3-25 | SI          |

**General Comment:**

Routine UIC inspection.

**Location****Lease Road:**

|                   |        |       |  |
|-------------------|--------|-------|--|
| Type              | Access |       |  |
| comment:          |        |       |  |
| Corrective Action | L      | Date: |  |
| Type              | Main   |       |  |
| comment:          |        |       |  |
| Corrective Action | L      | Date: |  |

Overall Good: ☒**Signs/Marker:**

|                    |          |       |  |
|--------------------|----------|-------|--|
| Type               | WELLHEAD |       |  |
| Comment:           |          |       |  |
| Corrective Action: |          | Date: |  |

Emergency Contact Number:

Comment: 970-675-3700

Corrective Action:

Date: \_\_\_\_\_

Overall Good: ☒**Spills:**

|      |      |        |  |  |
|------|------|--------|--|--|
| Type | Area | Volume |  |  |
|------|------|--------|--|--|

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Equipment:**

|                           |     |       |                 |
|---------------------------|-----|-------|-----------------|
| Type: Bradenhead          | # 1 |       | corrective date |
| Comment:                  |     |       |                 |
| Corrective Action:        |     | Date: |                 |
| Type: Ancillary equipment | # 1 |       |                 |
| Comment: WAG skid         |     |       |                 |
| Corrective Action:        |     | Date: |                 |
| Type: Deadman # & Marked  | # 4 |       |                 |
| Comment:                  |     |       |                 |
| Corrective Action:        |     | Date: |                 |

**Venting:**

|                    |    |       |  |
|--------------------|----|-------|--|
| Yes/No             | NO |       |  |
| Comment:           |    |       |  |
| Corrective Action: |    | Date: |  |

**Flaring:**

|          |  |  |
|----------|--|--|
| Type     |  |  |
| Comment: |  |  |

|                    |  |       |  |
|--------------------|--|-------|--|
| Corrective Action: |  | Date: |  |
|--------------------|--|-------|--|

Inspected Facilities

Facility ID: 229105

Type: WELL

API Number: 103-06187

Status: IJ

Insp. Status: SI

Underground Injection Control

UIC Violation:

Maximum Injection Pressure:

UIC Routine

Inj./Tube:

Pressure or inches of Hg 2064

Previous Test Pressure

MPP

(e.g. 30 psig or -30" Hg)

Inj Zone: WEBR

TC:

Pressure or inches of Hg 0

Previous Test Pressure

Last MIT: 08/24/2023

Brhd:

Pressure or inches of Hg 10

Previous Test Pressure

AnnMTReq:

Comment:

Routine UIC Inspection. Well shut in. No active injection at time of inspection.

Corrective Action:

Date:

Method of Injection: PUMP FEED

Test Type:

Tbg psi:

Csg psi:

BH psi:

Insp. Status:

Comment:

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Date Run: 5/13/2024 Doc [#693807304]

Page 4 of 5

Reclamation - Storm Water - Pit

Storm Water:

|                  |                 |                         |                       |               |                          |         |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
| Berms            | Pass            | Gravel                  | Pass                  |               |                          |         |

Comment:

Corrective Action:

Date:

Pits: ☐ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

|              |                             |   |
|--------------|-----------------------------|---|
| Document Num | Description                 | URL   |
| 693807305    | Inspection photos 5/10/2024 | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6545862">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6545862</a> |