

Inspection Photos
Location: Baughman # 6
Facility ID: 324843

[Related](#)
[Insp](#)
[MIT](#)
[GIS](#)
[Doc](#)
[COA](#)
[Wellbore](#)
[Orders](#)
[Bradenhead](#)

Surface Location API# 05-061-06452	Well Classification: OW	Status: SI - 8/2/2022
--	--------------------------------	------------------------------

[Well Name/No:](#) [BAUGHMAN #6](#) [Click Here for Transporter Gatherer Info](#)
(Click Well Name for Production Data)

[Operator:](#) [CHEMCO INC - 16520](#) Federal Or State Lease #:
(Click Operator Name for Company Detail Report)

Facility Status:	SI	Status Date	8/2/2022
FacilityID:	213091	LocationID:	324843
County:	KIOWA #061	Location:	NESW 2 19S45W 6
Field:	CAVALRY - #10340	Elevation:	3930 ft.
Planned Location:	1980FSL 1980 FWL	Lat/Long:	38.431572 / -102.429684
		Calculated From	Footages

Primary Well
Defined In

All
Designations

Reported Plugged

Out Of Service
Repurposed

Out Of Service

Inactive Exception

Noticed Inactive

Defined Inactive (SI)

Low Producing

BOE/MCFE/GC



Photo 1 –Scout Card, no well placard present

Photo 2 – Pump Jack

Inspection Photos
Location: Baughman # 6
Facility ID: 324843



Photo 3 – Unused equipment




Photo 4 – Crow/Bird nest

Inspection Photos
Location: Baughman # 6
Facility ID: 324843



Photo 5 – Unused equipment




Photo 6 – Stained soils

Inspection Photos
Location: Baughman # 6
Facility ID: 324843



Photo 7 – Heater Treater new dirt berm.

Photo 8 – Tank Battery

Inspection Photos
Location: Baughman # 6
Facility ID: 324843



Photo 9 – Tank Battery



Photo 10 – Tank Battery