

Inspection Photos
 Location: Wear 3
 Facility ID: 324847

Surface Location		Well Classification: OW	Status: PR - 9/1/2023
Well Name/No:	WEAR #3	Click Here for Transporter Gatherer Info	
<small>(Click Well Name for Production Data)</small>			
Operator:	CHEMCO INC - 16520	Federal Or State Lease #:	
<small>(Click Operator Name for Company Detail Report)</small>			
Facility Status:	PR	Status Date	9/1/2023
FacilityID:	213124	LocationID:	324847
County:	KIOWA #061	Location:	SESE 3 19S45W 6
Field:	BRANDON - #7500	Elevation:	3918 ft.
Planned Location:	660FSL 660 FEL	Lat/Long:	38.427872 / -102.438824
As Drilled Location:	Footages Not Available	Lat/Long:	38.427852 / -102.438838
		Source:	Field Measured
Sample Site Data			

All Designations	Date
Reported Plugged	N
Out Of Service Repurposed	N
Out Of Service	N
Inactive Exception	N
Noticed Inactive	N
Defined Inactive	N
Low Producing	Y

BOE/MCFE/GOR Calculation Production for Previous 12 Months
February 2023 - January 2024
Total Oil Produced (Barrels)
Total Gas Produced (MCF)



Photo 1 –Scout Card, no well placard present

Photo 2 – Pump Jack

Inspection Photos
Location: Wear 3
Facility ID: 324847




Photo 3 – Ladder with mechanic wire

Photo 4 – Oil stained soils

Inspection Photos
Location: Wear 3
Facility ID: 324847



Photo 5 – Impacted soils adjacent to wellhead

Photo 6 – Tank Battery / Treater

Inspection Photos
Location: Wear 3
Facility ID: 324847



Photo 7 – Leaking piping at Treater.

Photo 8 – Impacted soils in Secondary Containment

Inspection Photos
Location: Wear 3
Facility ID: 324847



Photo 9 – Impacted soils in Secondary Containment

Photo 10 – Impacted soils in Secondary Containment