

Inspection Photos  
Location: Donohoe 4A-2  
Facility ID: 384662



May 8, 2024 at 11:38:35 AM  
+38.434784, -102.430123  
ECMC



May 8, 2024 at 11:38:51 AM  
+38.434701, -102.430176  
ECMC

Photo 1 –Well Placard

Photo 2 – Pump Jack

**Inspection Photos**  
**Location: Donohoe 4A-2**  
**Facility ID: 384662**



**Photo 3 – Machine Guarding not maintained**

**Photo 4 – Oil and Coolant bottles stored in pump jack frame**

**Inspection Photos**  
**Location: Donohoe 4A-2**  
**Facility ID: 384662**



**Photo 5 – Well head with rag on stuffing box**

**Photo 6 – Tank Battery, Secondary containment not adequate**

**Inspection Photos**  
**Location: Donohoe 4A-2**  
**Facility ID: 384662**



**Photo 7 – Impacted soils along berm**

**Photo 8 – Unused equipment and stained soils**

**Inspection Photos**  
**Location: Donohoe 4A-2**  
**Facility ID: 384662**



**Photo 9 – Impacted soils at Heater Treater**



**Photo 10 – Hole in berm**