

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/08/2024

Submitted Date:

05/13/2024

Document Number:

710500247

FIELD INSPECTION FORMLoc ID 324843 Inspector Name: Sanchez, Chris On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

ECMC Operator Number: 16520

Name of Operator: CHEMCO INC

Address: 6970 SOUTH HOLLY CIR STE 206

City: CENTENNIAL State: CO Zip: 80112

Status Summary:

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

5 Number of Comments

0 Number of Corrective Actions

☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Welsh, Brian		brian.welsh@state.co.us	
Hickey, Mike		michael.hickey@state.co.us	
Costa, Ryan		ryan.costa@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
213091	WELL	SI	08/02/2022	OW	061-06452	BAUGHMAN 6	EI
485257	SPILL OR RELEASE	AC	10/13/2023		-	SPILL/RELEASE POINT	EI

General Comment:

This is an Environmental Inspection for the Baughman #6, Well location Located in Kiowa County, CO.
On 10/5/2023, Ryan Costa conducted a follow up inspection Document # 713600282 of the previous inspection #713600280.

Location				
Overall Good: <input type="checkbox"/>				
Emergency Contact Number:				
Comment:		No well placard was observed at the time of inspection		Date: _____
Corrective Action:				
Good Housekeeping:				
Type	UNUSED EQUIPMENT			
Comment:	Unused equipment next to the wellhead and pump jack			
Corrective Action:				Date:
Overall Good: <input type="checkbox"/>				
Spills:				
Type	Area	Volume		
In Containment: No				
Comment:		There is oil-stained soils at the pump jack, separator and tank battery,		
<input type="checkbox"/> Multiple Spills and Releases?				
Fencing/:				
Type				
Comment:				
Corrective Action:				Date:
Equipment:				corrective date
Type: Pump Jack	#			
Comment:	Bird Nest Observed in Pumping Unit Horsehead, Crow's Nest			
Corrective Action:				Date:
Venting:				
Yes/No				
Comment:				
Corrective Action:				Date:
Flaring:				
Type				
Comment:				
Corrective Action:				Date:

Inspected Facilities									
Facility ID:	213091	Type:	WELL	API Number:	061-06452	Status:	SI	Insp. Status:	EI
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									
Facility ID:	485257	Type:	SPILL OR	API Number:	-	Status:	AC	Insp. Status:	EI
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									

ECMC Comments		
Comment	User	Date
There is an open Spill, Spill Facility ID 485257 on the location. Impacted soils still present at wellhead, separator and tank battery	sanchezcc	05/13/2024

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
710500267	Inspection # 710500247 Location Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6546478