

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/08/2024

Submitted Date:

05/13/2024

Document Number:

710500249

**FIELD INSPECTION FORM**Loc ID 324836 Inspector Name: Sanchez, Chris On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**

ECMC Operator Number: 16520

Name of Operator: CHEMCO INC

Address: 6970 SOUTH HOLLY CIR STE 206

City: CENTENNIAL State: CO Zip: 80112

**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

4 Number of Comments

0 Number of Corrective Actions

☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Costa, Ryan		ryan.costa@state.co.us	
Hickey, Mike		michael.hickey@state.co.us	
Welsh, Brian		brian.welsh@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
213031	WELL	PR	11/01/2022	OW	061-06392	BAUGHMAN 7	EI
324836	LOCATION	AC			-	BAUGHMAN-619S45W 2SWSW	EI

**General Comment:**

This is an Environmental Inspection for the Baughman # 7, well location located in Kiowa County, Co  
On 10/5/2023, Ryan Costa conducted a follow up inspection Document # 713600288 of the previous inspection #713600090.

**Location****Lease Road:**

Type			
comment:			
Corrective ActionL		Date:	

Overall Good: ☐**Emergency Contact Number:**

Comment:	No well placard on site, Tank Labels are illegible	Date:	
Corrective Action:			

**Good Housekeeping:**

Type	UNUSED EQUIPMENT		
Comment:	There are three 55-gallon drums located on the location, one in containment at the wellhead, one not in containment and one that has blown across the location and is now off the east edge of the well pad.		
Corrective Action:		Date:	

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: There are signs of impacted soils at the wellhead, pump jack and in the secondary containment of the tank battery.

☐ Multiple Spills and Releases?**Fencing/:**

Type	PUMP JACK		
Comment:	Machine Guarding not maintained		
Corrective Action:		Date:	

**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities				
Facility ID: 213031	Type: WELL	API Number: 061-06392	Status: PR	Insp. Status: EI
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				
Facility ID: 324836	Type: LOCATION	API Number: -	Status: AC	Insp. Status: EI
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
710500263	Inspection # 710500249 Location Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6546479">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6546479</a>