

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/08/2024

Submitted Date:

05/13/2024

Document Number:

710500251**FIELD INSPECTION FORM**Loc ID 324847 Inspector Name: Sanchez, Chris On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**ECMC Operator Number: 16520Name of Operator: CHEMCO INCAddress: 6970 SOUTH HOLLY CIR STE 206City: CENTENNIAL State: CO Zip: 80112**Status Summary:**

- ☐
- THIS IS A FOLLOW UP INSPECTION
-
- ☐
- FOLLOW UP INSPECTION REQUIRED
-
- ☐
- NO FOLLOW UP INSPECTION REQUIRED

Findings:7 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Hickey, Mike		michael.hickey@state.co.us	
Welsh, Brian		brian.welsh@state.co.us	
Costa, Ryan		ryan.costa@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
213124	WELL	PR	09/01/2023	OW	061-06485	WEAR 3	EI
482453	TANK BATTERY	AC			-	Wear #3 Tank Battery	EI

General Comment:

This is an Environmental Inspection for the Wear # 3 well site located in Kiowa County, Co. This inspection is in response to Landowner Complaint Document # 403772929

This is also a follow up to Environmental Inspection # 710500048.

LocationOverall Good: ☐

Emergency Contact Number:

Comment: At the time of inspection, there were no well placards at the well pad or offsite tank battery

Corrective Action:

Date:

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: Impacted soils observed at the wellhead, separator and tank battery

☐ Multiple Spills and Releases?**Fencing/:**

Type	PUMP JACK		
Comment:	Machine Guarding not maintained		
Corrective Action:		Date:	

Equipment:

Type: Pump Jack	#		corrective date
Comment:	Ladder attached to Pump Jack is broken. Ladder held to unit with mechanic wire.		
Corrective Action:		Date:	
Type: Other	#		
Comment:	There is a 2-inch flowline riser east of the tank battery that has impacted soils		
Corrective Action:		Date:	
Type: Vertical Heated Separator	#		
Comment:	Connections to separator appear to be leaking, piping is wet, impacted soils observed at the base of separator.		
Corrective Action:		Date:	

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

