

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/08/2024

Submitted Date:

05/13/2024

Document Number:

710500253

FIELD INSPECTION FORMLoc ID 324848 Inspector Name: Sanchez, Chris On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

ECMC Operator Number: 16520

Name of Operator: CHEMCO INC

Address: 6970 SOUTH HOLLY CIR STE 206

City: CENTENNIAL State: CO Zip: 80112

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

5 Number of Comments

0 Number of Corrective Actions

☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Costa, Ryan		ryan.costa@state.co.us	
Welsh, Brian		brian.welsh@state.co.us	
Hickey, Mike		michael.hickey@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
213127	WELL	SI	12/01/2021	OW	061-06488	BAUGHMAN 8	EI
324848	LOCATION	AC			-	BAUGHMAN-619S45W 2SESW	EI

General Comment:

This is an Environmental Inspection for the Baughman # 8 well location located in Kiowa County, Co

On 10/09/2023 Ryan Costa conducted a follow up inspection document # 713600284 to a previous reclamation inspection document # 713600092

LocationOverall Good: ☐

Emergency Contact Number:

Comment: At the time of inspection, there were no well placards at the well pad or offsite tank battery

Corrective Action:

Date:

Good Housekeeping:

Type TRASH

Comment: Debris and trash observed in pump jack frame.

Corrective Action:

Date:

Overall Good: ☐**Spills:**

Type Area Volume

In Containment: No

Comment: There are signs of impacted soils at the wellhead, pump jack, historical separator location and in the secondary containment of the tank battery.

☐ Multiple Spills and Releases?**Fencing/:**

Type

Comment: Machine guarding not maintained

Corrective Action:

Date:

Tanks and Berms:

Contents # Capacity Type Tank ID SE GPS

Comment:

Corrective Action:

Date:

Paint

Condition

Other (Content)

Other (Capacity)

Other (Type)

Berms

Type Capacity Permeability (Wall) Permeability (Base) Maintenance

Earth

Comment: Secondary containment not adequate

Corrective Action:

Date:

Venting:

Yes/No

Comment:

Corrective Action:

Date:

Flaring:			
Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities				
Facility ID: 213127	Type: WELL	API Number: 061-06488	Status: SI	Insp. Status: EI
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				
Facility ID: 324848	Type: LOCATION	API Number: -	Status: AC	Insp. Status: EI
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
710500264	Inspection # 710500253 Location Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6546481