

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/08/2024

Submitted Date:

05/13/2024

Document Number:

710500259

FIELD INSPECTION FORMLoc ID 324804 Inspector Name: Sanchez, Chris On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

ECMC Operator Number: 95620

Name of Operator: WESTERN OPERATING COMPANY

Address: 1165 DELAWARE STREET #200

City: DENVER State: CO Zip: 80204

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

6 Number of Comments

0 Number of Corrective Actions

☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

| Contact Name | Phone | Email | Comment |
|---------------|----------------|----------------------------|---------|
| Costa, Ryan | | ryan.costa@state.co.us | |
| James, Steven | (303) 893-2438 | steve@westernoperating.com | |
| Hart, Dale | 719-688-1638 | dale@westernoperating.com | |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|----------|--------|-------------|------------|---------|-----------------------------|-------------|
| 470688 | Location | AC | | | - | KING-PYLES-619S45W 8SWSE | EI |

General Comment:

This is a follow up Environmental Inspection for the King Plyes #4 Tank Battery Spill Remediation, Location ID 480894, Remediation # 21723, located in Kiowa County, Co

On 2/27/2024 Ryan Costa conducted a reclamation inspection of the KING-PYLES #4 wellsite and off-site tank battery. This inspection is in response to complaint #403694753

| | | | | | |
|--|---|---------------------|---------------------|-------------|-------------|
| Location | | | | | |
| Overall Good: <input type="checkbox"/> | | | | | |
| Emergency Contact Number: | | | | | |
| Comment: | | | | | Date: _____ |
| Corrective Action: | | | | | |
| Good Housekeeping: | | | | | |
| Type | UNUSED EQUIPMENT | | | | |
| Comment: | There are two tanks located in the Tank Battery that are not is service. Remove tanks and comply with Rule 606. | | | | |
| Corrective Action: | | | | | Date: |
| Overall Good: <input type="checkbox"/> | | | | | |
| Spills: | | | | | |
| Type | Area | Volume | | | |
| In Containment: No | | | | | |
| Comment: | | | | | |
| <input type="checkbox"/> Multiple Spills and Releases? | | | | | |
| Tanks and Berms: | | | | | |
| Contents | # | Capacity | Type | Tank ID | SE GPS |
| CRUDE OIL | 5 | 300 BBLS | STEEL AST | | , |
| Comment: | There are five tanks in the tank battery, two 300 bbl.. One labeled crude oil and the other labeled produced water, crude oil. There is one 400 bbl. tank labeled produced water, crude oil. In addition, two 200 bbl. tanks that are not in service. | | | | |
| Corrective Action: | | | | | Date: |
| Paint | | | | | |
| Condition | Adequate | | | | |
| Other (Content) | water | | | | |
| Other (Capacity) | one 400 bbl and two 200 bbl | | | | |
| Other (Type) | Ont in service | | | | |
| Berms | | | | | |
| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance | |
| Earth | | | | | |
| Comment: | The secondary containment is an earthen berm | | | | |
| Corrective Action: | | | | | Date: |
| Venting: | | | | | |
| Yes/No | | | | | |
| Comment: | | | | | |
| Corrective Action: | | | | | Date: |
| Flaring: | | | | | |
| Type | | | | | |
| Comment: | | | | | |

| | | | |
|--------------------|--|-------|--|
| Corrective Action: | | Date: | |
|--------------------|--|-------|--|

