

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

04/24/2024

Submitted Date:

05/07/2024

Document Number:

709100288

**FIELD INSPECTION FORM**

Loc ID 337807 Inspector Name: Heibel, Krystal On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

ECMC Operator Number: 10699  
Name of Operator: OWN RESOURCES OPERATING LLC  
Address: 305 S RIDGE STREET #6279  
City: BRECKENRIDGE State: CO Zip: 80424

**Findings:**

- 4 Number of Comments
- 2 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Abdul Elnajdi		abdul.elnajdi@state.co.us	
Kyle Waggoner		kyle.waggoner@state.co.us	
Kilian Collins		kilian.collins@state.co.us	
Krystal Heibel		krystal.heibel@state.co.us	
Dolezal, Pat		pat.dolezal@ownresources.com	<a href="#">Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
288758	WELL	PR	08/01/2008	GW	125-10614	KNODEL 13-16	EI

**General Comment:**

On April 24, 2024, ECMC Environmental Unit Staff Krystal Heibel, Kilian Collins, and Abdul Alnajdi inspected the Knodel 13-16 location (Location ID:337807).

This is an environmental inspection. Any corrective actions from previous inspections that have not been addressed are still applicable.

**Location**

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Good Housekeeping:**

Type: UNUSED EQUIPMENT

Comment: Unused equipment (metal post) stored within secondary containment.

Corrective Action: Comply with Rule 606

Date: 08/07/2024

Overall Good:

**Spills:**

Type	Area	Volume

In Containment: No

Comment:

Multiple Spills and Releases?

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
Comment:					
Corrective Action:					Date:

Paint

Condition:

Other (Content):

Other (Capacity):

Other (Type):

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment: Burrows observed surrounding the location and near secondary containment.				
Corrective Action: Repair or install berms or other secondary containment devices per Rule 603.o.				Date: 08/07/2024

**Venting:**

Yes/No:

Comment:

Corrective Action:

Date:

**Flaring:**

Type: <input type="text"/>	
Comment: <input type="text"/>	
Corrective Action: <input type="text"/>	Date: <input type="text"/>

**Inspected Facilities**

Facility ID: 288758 Type: WELL API Number: 125-10614 Status: PR Insp. Status: EI

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403782447	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6539218">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6539218</a>
709100289	Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6539211">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6539211</a>