

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

05/14/2024

Submitted Date:

05/14/2024

Document Number:

699505803

FIELD INSPECTION FORM

Loc ID: 450043 Inspector Name: MEDINA, JUSTIN On-Site Inspection: 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Findings:

3 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Operator Information:

ECMC Operator Number: 10459
Name of Operator: EXTRACTION OIL & GAS INC
Address: 555 17TH STREET SUITE 3700
City: DENVER State: CO Zip: 80202

Contact Information:

| Contact Name | Phone | Email | Comment |
|--------------|-------|-------------------------------|---------|
| | | Inspections@civiresources.com | |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|---------------------|-------------|
| 450045 | WELL | PR | 04/01/2023 | OW | 001-10032 | PC 1S-66-2928 12NH | PR |
| 450046 | WELL | PR | 04/01/2023 | OW | 001-10033 | PC 1S-66-2928 3NH | PR |
| 450047 | WELL | PR | 04/01/2023 | OW | 001-10034 | PC 1S-66-2928 17NH | PR |
| 450052 | WELL | PR | 04/01/2023 | OW | 001-10039 | PC 1S-66-2928 20CDH | PR |
| 450053 | WELL | PR | 04/01/2023 | OW | 001-10040 | PC 1S-66-2928 2CDH | PR |
| 450054 | WELL | PR | 04/01/2023 | OW | 001-10041 | PC 1S-66-2928 7CDH | PR |
| 450055 | WELL | PR | 04/01/2023 | OW | 001-10042 | PC 1S-66-2928 14CDH | PR |
| 450056 | WELL | PR | 04/01/2023 | OW | 001-10043 | PC 1S-66-2928 9NH | PR |
| 450057 | WELL | PR | 04/01/2023 | OW | 001-10044 | PC 1S-66-2928 19NH | PR |
| 450058 | WELL | PR | 09/01/2023 | OW | 001-10045 | PC 1S-66-2928 5NH | PR |
| 450059 | WELL | PR | 04/01/2023 | OW | 001-10046 | PC 1S-66-2928 8NH | PR |

General Comment:

There have been no changes to equipment on location since previous inspection.

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good:

Spills:

| Type | Area | Volume | | |
|------|------|--------|--|--|
| | | | | |

In Containment: No

Comment:

Multiple Spills and Releases?

Venting:

| | | | |
|--------------------|----|-------|--|
| Yes/No | NO | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Flaring:

| | | |
|--------------------|--|-------|
| Type | | |
| Comment: | | |
| Corrective Action: | | Date: |

Inspected Facilities

Facility ID: 450045 Type: WELL API Number: 001-10032 Status: PR Insp. Status: PR

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 450046 Type: WELL API Number: 001-10033 Status: PR Insp. Status: PR

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 450047 Type: WELL API Number: 001-10034 Status: PR Insp. Status: PR

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 450052 Type: WELL API Number: 001-10039 Status: PR Insp. Status: PR

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 450053 Type: WELL API Number: 001-10040 Status: PR Insp. Status: PR

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 450054 Type: WELL API Number: 001-10041 Status: PR Insp. Status: PR

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 450055 Type: WELL API Number: 001-10042 Status: PR Insp. Status: PR

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 450056 Type: WELL API Number: 001-10043 Status: PR Insp. Status: PR

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 450057 Type: WELL API Number: 001-10044 Status: PR Insp. Status: PR

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 450058 Type: WELL API Number: 001-10045 Status: PR Insp. Status: PR

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 450059 Type: WELL API Number: 001-10046 Status: PR Insp. Status: PR

Producing Well

| | |
|--------------------|-------|
| Comment: <u>PR</u> | |
| Corrective Action: | Date: |

BradenHead

Date of Last Brhd Test: 04/04/2023 Annual Brhd Completed? _____

Last Brhd Test Results Initial Surf Csg Pressure: 4 Fluid Type: _____

End Surf Csg Pressure: 0

Comment: _____

Corrective Action: _____ Date: _____

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

ECMC Comments

| Comment | User | Date |
|---|---------|------------|
| At time of inspection location appears to be in compliance with ECMC rules. At time of inspection weather conditions were clear, calm, warm. | medinaj | 05/14/2024 |

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|---------------------|---|
| 699505804 | inspection pictures | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6547873 |