

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

05/15/2024

Submitted Date:

05/15/2024

Document Number:

716400105

**FIELD INSPECTION FORM**

Loc ID 317765 Inspector Name: Revas, Robbie On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Operator Information:**

ECMC Operator Number: 46290  
Name of Operator: KP KAUFFMAN COMPANY INC  
Address: 1700 LINCOLN ST STE 4550  
City: DENVER State: CO Zip: 80203

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

- 9 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Silver, Randy		randy.silver@state.co.us	
,		cogcc@kpk.com	<a href="#">All Inspections</a>
,		rwatzman@kpk.com	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
239943	WELL	SI	11/01/2023	OW	123-07731	A L LUFT 1	SI

**General Comment:**

[This is a wellsite inspection due to a complaint Doc # 403773135.](#)

**Location**

<b>Lease Road:</b>			
Type	Access		
comment:	The bridge between the A L Luft 1 Wellsite & the A L Luft 2 well is in disrepair/rotting and needs to be addressed. This Compliance issue was Documented in a previous Complaint on 11-15-2021 Form 18 Doc # 402865422, FIR Doc # 693505825 with a CA date of 12-15-2021 and has continued to rot.		
Corrective Action:	Comply with 600 rules.	Date:	06/15/2024

Overall Good:

<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:	adequate		
Corrective Action:		Date:	

<b>Emergency Contact Number:</b>			
Comment:	<input style="width: 100%;" type="text"/>		
Corrective Action:	<input style="width: 100%;" type="text"/>		Date: _____

Overall Good:

<b>Spills:</b>			
Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

<b>Fencing/:</b>			
Type			
Comment:			
Corrective Action:		Date:	

<b>Equipment:</b>			corrective date
Type: Prime Mover	# 1		
Comment:	Gas engine		
Corrective Action:		Date:	
Type: Pump Jack	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:			
Corrective Action:		Date:	

<b>Venting:</b>			
Yes/No	NO		
Comment:			
Corrective Action:		Date:	

<b>Flaring:</b>			
-----------------	--	--	--

Type		
Comment:		
Corrective Action:		Date:

**Inspected Facilities**

Facility ID: 239943 Type: WELL API Number: 123-07731 Status: SI Insp. Status: SI

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: \_\_\_\_\_

Comment: SI

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**BradenHead**

Date of Last Brhd Test: 01/22/2024 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: \_\_\_\_\_

End Surf Csg Pressure: 0

Comment: Plumbed to surface

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

**ECMC Comments**

Comment	User	Date
<p>ECMC Inspection Report Summary                      On Thursday 5-9-2024 at approximately 1430 hrs. I, Inspector Robbie Revas,                      Conducted an on-site inspection: This is a wellsite inspection due to a complaint Doc #                      403773135.                      Operator: KP Kauffman                      Location name: A L Luft-61N67W                      Location ID # 317765                      Well Name: A L Luft 1                      API # 05-123-07731                      County: Weld                      Weather: Clear &amp; windy                      Location: Dry                      While there, I observed a wellsite, SI at the time of the inspection.                      During this inspection, I observed the following possible compliance issue:                      600 Access: CA date 6-15-2024.                      See attached photos.                      A follow up site inspection is needed to ensure that the addressed                      Compliance issues comply with ECMC rules.                      Any Corrective Actions from previous inspections not addressed are still applicable.</p>	revasr	05/15/2024

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
716400106	Location photos	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6549257">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6549257</a>