

Storm Water Management and Erosion control

Location Name: TEP ROCKY MOUNTAIN LLC BATTLEMENT MESA PARTNERS GV 82-5 Pad

Location ID: 334825



Location Overview: Location is within High Priority/Density/NSO/Black Bear Habitat areas & Bald Eagle Roost sites. Location is within Rule 411a Surface Water Internal Buffer & Rule 411b Generalized Internal Buffer. Location is approximately 39 yards from the Colorado River.

Section/Township/Range: 5 7S95W



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Storm Water Management and Erosion control

Location Name: TEP ROCKY MOUNTAIN LLC BATTLEMENT MESA PARTNERS GV 82-5 Pad

Location ID: 334825



Location Overview:



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Storm water Management and Erosion control

Location Name: TEP ROCKY MOUNTAIN LLC BATTLEMENT MESA PARTNERS GV 82-5 Pad

Location ID: 334825



North West corner of location.



North East corner of location.



South West corner of location.



South East corner of location.

Storm water Management and Erosion control

Location Name: TEP ROCKY MOUNTAIN LLC BATTLEMENT MESA PARTNERS GV 82-5 Pad

Location ID: 334825



Photo # 7073 Location surface lacks stabilization/compaction with insufficient vehicle tracking BMPs in place to minimize transportation of sediment



Photo # 7074 Location surface lacks stabilization/compaction with insufficient vehicle tracking BMPs in place to minimize transportation of sediment

Storm water Management and Erosion control

Location Name: TEP ROCKY MOUNTAIN LLC BATTLEMENT MESA PARTNERS GV 82-5 Pad

Location ID: 334825



Photo # 7075 Location surface lacks stabilization/compaction with insufficient vehicle tracking BMPs in place to minimize transportation of sediment



Photo # 7076 Lack of stabilization/compaction/insufficient BMP's

Storm water Management and Erosion control

Location Name: TEP ROCKY MOUNTAIN LLC BATTLEMENT MESA PARTNERS GV 82-5 Pad

Location ID: 334825



Photo # 7077 Lack of stabilization/compaction/insufficient BMP's



Photo # 7078 Lack of stabilization/compaction/insufficient BMP's

Storm water Management and Erosion control

Location Name: TEP ROCKY MOUNTAIN LLC BATTLEMENT MESA PARTNERS GV 82-5 Pad

Location ID: 334825



Photo # 7079 Lack of stabilization/compaction/insufficient BMP's



Photo # 7080 Lack of stabilization/compaction/insufficient BMP's

Storm water Management and Erosion control

Location Name: TEP ROCKY MOUNTAIN LLC BATTLEMENT MESA PARTNERS GV 82-5 Pad

Location ID: 334825



Photo # 7081 Lack of stabilization/compaction/insufficient BMP's



Photo # 7082 Lack of stabilization/compaction/insufficient BMP's

Storm water Management and Erosion control

Location Name: TEP ROCKY MOUNTAIN LLC BATTLEMENT MESA PARTNERS GV 82-5 Pad

Location ID: 334825



Photo # 7083 Lack of stabilization/compaction/insufficient BMP's



Photo # 7084 Lack of stabilization/compaction/insufficient BMP's

Storm water Management and Erosion control

Location Name: TEP ROCKY MOUNTAIN LLC BATTLEMENT MESA PARTNERS GV 82-5 Pad

Location ID: 334825



Photo # 7085 Lack of stabilization/compaction/insufficient BMP's



Photo # 7086 Lack of stabilization/compaction/insufficient BMP's

Storm water Management and Erosion control

Location Name: TEP ROCKY MOUNTAIN LLC BATTLEMENT MESA PARTNERS GV 82-5 Pad

Location ID: 334825



**Photo # 7087 Lack of stabilization & erosion on cut slope
/insufficient BMP's**



**Photo # 7088 Lack of stabilization & erosion on cut slope
/insufficient BMP's**

Storm water Management and Erosion control

Location Name: TEP ROCKY MOUNTAIN LLC BATTLEMENT MESA PARTNERS GV 82-5 Pad

Location ID: 334825



**Photo # 7089 Lack of stabilization & erosion on cut slope
/insufficient BMP's**



**Photo # 7090 Lack of stabilization & erosion on cut slope
/insufficient BMP's**

Storm water Management and Erosion control

Location Name: TEP ROCKY MOUNTAIN LLC BATTLEMENT MESA PARTNERS GV 82-5 Pad

Location ID: 334825



**Photo # 7091 Lack of stabilization & erosion on cut slope
/insufficient BMP's**



**Photo # 7092 Lack of stabilization & erosion on cut slope
/insufficient BMP's**

Storm water Management and Erosion control

Location Name: TEP ROCKY MOUNTAIN LLC BATTLEMENT MESA PARTNERS GV 82-5 Pad

Location ID: 334825



**Photo # 7093 Lack of stabilization & erosion on cut slope
/insufficient BMP's**



**Photo # 7094 Lack of stabilization & erosion on cut slope
/insufficient BMP's**

Storm water Management and Erosion control

Location Name: TEP ROCKY MOUNTAIN LLC BATTLEMENT MESA PARTNERS GV 82-5 Pad

Location ID: 334825



**Photo # 7095 Lack of stabilization & erosion on cut slope
/insufficient BMP's**



**Photo # 7096 Lack of stabilization & erosion on cut slope
/insufficient BMP's**

Storm water Management and Erosion control

Location Name: TEP ROCKY MOUNTAIN LLC BATTLEMENT MESA PARTNERS GV 82-5 Pad

Location ID: 334825



**Photo # 7097 Lack of stabilization & erosion on cut slope
/insufficient BMP's**



**Photo # 7098 Lack of stabilization & erosion on cut slope
/insufficient BMP's**

Storm water Management and Erosion control

Location Name: TEP ROCKY MOUNTAIN LLC BATTLEMENT MESA PARTNERS GV 82-5 Pad

Location ID: 334825



May 15, 2024 at 2:05:10 PM



May 15, 2024 at 2:05:21 PM

**Photo # 7099 Lack of stabilization & erosion on cut slope
/insufficient BMP's**

**Photo # 7100 Lack of stabilization & erosion on cut slope
/insufficient BMP's**

Storm water Management and Erosion control

Location Name: TEP ROCKY MOUNTAIN LLC BATTLEMENT MESA PARTNERS GV 82-5 Pad

Location ID: 334825



Photo # 7101 Tunnel erosion on lease road (approximately 6/10th of a mile from location)



Photo # 7102 Tunnel erosion on lease road (approximately 6/10th of a mile from location)