

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC BATTLEMENT MESA PARTNERS GV 82-5 Pad

Location ID: 334825



Photo # 7051 From entrance to location




Photo # 7052 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC BATTLEMENT MESA PARTNERS GV 82-5 Pad

Location ID: 334825



Photo # 7053 Location



Photo # 7054 Location



Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC BATTLEMENT MESA PARTNERS GV 82-5 Pad

Location ID: 334825



Photo # 7055 Location



Photo # 7056 Location



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC BATTLEMENT MESA PARTNERS GV 82-5 Pad

Location ID: 334825



Photo # 7057 Location



Photo # 7058 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC BATTLEMENT MESA PARTNERS GV 82-5 Pad

Location ID: 334825



Photo # 7059 Location




Photo # 7060 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC BATTLEMENT MESA PARTNERS GV 82-5 Pad

Location ID: 334825



Photo # 7061 Possible wellhead leak on W 15-5 well



Photo # 7062 Possible wellhead leak on W 15-5 well

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC BATTLEMENT MESA PARTNERS GV 82-5 Pad

Location ID: 334825



Photo # 7063 Possible wellhead leak on W 15-5 well



Photo # 7064 Possible wellhead leak on W 15-5 well

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC BATTLEMENT MESA PARTNERS GV 82-5 Pad

Location ID: 334825



**Photo # 7065 Barbed wire laying on ground/wildlife hazard
(NW corner of location near separator units)**



**Photo # 7066 Barbed wire laying on ground/wildlife hazard
(NW corner of location near separator units)**

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC BATTLEMENT MESA PARTNERS GV 82-5 Pad

Location ID: 334825



**Photo # 7067 Barbed wire laying on ground/wildlife hazard
(NW corner of location near separator units)**



**Photo # 7068 Barbed wire laying on ground/wildlife hazard
(NW corner of location near separator units)**

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC BATTLEMENT MESA PARTNERS GV 82-5 Pad

Location ID: 334825



**Photo # 7069 Barbed wire laying on ground/wildlife hazard
(NW corner of location near separator units)**



**Photo # 7070 Rupture disc vent line lacks cap/does not
comply with CECMC pressure safety device rules**

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC BATTLEMENT MESA PARTNERS GV 82-5 Pad

Location ID: 334825



Photo # 7071 PRV does not comply with CECMC pressure safety device rules



Photo # 7072 Some fluid in 2 of 3 chemical tank containments, may need maintenance in the near future.