

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/01/2024

Submitted Date:

05/08/2024

Document Number:

707800924

FIELD INSPECTION FORMLoc ID 449274 Inspector Name: Ramsey, Scott On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

ECMC Operator Number: 10805

Name of Operator: FULCRUM ENERGY OPERATING LLC

Address: 240 SAINT PAUL STREET SUITE 502

City: DENVER State: CO Zip: 80206

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

9 Number of Comments

3 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
annalee Penner		annalee@fulcrumef.com	
Fulcrum		inspections@fulcrumeo.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
449275	WELL	SI	12/01/2023	OW	057-06598	REU 0681 1-23H2	SI

General Comment:**ECMC Inspection Report Summary**

On Wednesday 5/1/2024, I, Inspector Scott Ramsey, conducted a routine inspection at REU 0681, at Location # 449274 in Jackson county Colorado.

Any Corrective Actions from previous Inspections that have not been addressed are still applicable.

While there, I observed normal operations. This location is within or in close proximity to a CPW Density/High Priority Habitat, black bear, NSO habitat, Wildlife black bear Management and Density habitat.

During this inspection the following possible compliance issues were observed:

1. Lack of battery signage
2. Random debris
3. Chemical containment full of fluid not sufficient to contain possible spill

Refer to photograph of observed compliance issue.

A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.

This is a summary of inspection report.

LocationOverall Good: ☐**Signs/Marker:**

Type	BATTERY		
Comment:	Lack of battery signage		
Corrective Action:	Provide proper signage	Date:	06/19/2024
Type	CONTAINERS		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment: Fulcrum 911/970-594-0477

Corrective Action:

Date: _____

Good Housekeeping:

Type	OTHER		
Comment:	Chemical containment full of fluid not sufficient to contain possible spill		
Corrective Action:	Evacuate fluids in containments to provide adequate space in case of a spill	Date:	05/24/2024
Type	DEBRIS		
Comment:	Random debris		
Corrective Action:	Remove debris	Date:	05/24/2024

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Equipment:**

Type: Ancillary equipment	# 1		corrective date
Comment:	chemical tank in plastic containment		
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:		Date:	
Type: Pump Jack	# 1		

Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	# 1		
Comment:			
Corrective Action:		Date:	
Type: Emission Control Device	# 2		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	1	OTHER			,	
Comment:						
Corrective Action:						Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)	625 BBLS	
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal		Walls Sufficient	Base Sufficient	
Comment:	Containment has fluid in it			
Corrective Action:				
			Date:	

Contents	#	Capacity	Type	Tank ID	SE GPS	
CRUDE OIL	2	OTHER	STEEL AST		,	
Comment:						
Corrective Action:						Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)	625 BBLS	
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal		Walls Sufficient	Base Sufficient	
Comment:	Containment has fluid in it			
Corrective Action:				
			Date:	

Inspected Facilities									
Facility ID:	449275	Type:	WELL	API Number:	057-06598	Status:	SI	Insp. Status:	SI
Idle Well									
Purpose: <input checked="" type="checkbox"/> Shut In <input type="checkbox"/> Temporarily Abandoned Reminder: _____									
Comment: <input type="text" value="Last produced 12/2023"/>									
Corrective Action: <input type="text"/> Date: _____									

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Ditches				
Gravel						
		Gravel				
Berms						

Comment:

Corrective Action:

Date:

Pits: ☒ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403785951	INSPECTION SUBMITTED	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6542645
707800940	Photo log	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6542637