

Inspection Photos

API: 061-06403

Operator: STRACHAN EXPLORATION INC

Inspection Date: 5/8/2024



Inspection Photos



Photo 1. Facing toward the offsite tank battery location. It appears some work has started at the tank battery but is incomplete. No sign has been installed. The fence is not adequate to prevent livestock entry and there is no gate at the red arrow.



Inspection Photos



May 8, 2024
+38.469257,-103.099579

Photo 2. Facing southwest at the wellsite.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

API: 061-06403 | Date: 5/8/2024

Inspection Photos



Photo 3. Facing toward the tank. The berm around the tank has been rebuilt. The sides of the berm are not compacted.



Inspection Photos



Photo 4. The well sign is faded and does not meet the signage requirements. Previous corrective action was not completed.

