

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

05/08/2024

Submitted Date:

05/10/2024

Document Number:

713601025

**FIELD INSPECTION FORM**

Loc ID 324840 Inspector Name: COSTA, RYAN On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

ECMC Operator Number: 83130  
Name of Operator: STRACHAN EXPLORATION INC  
Address: 992 S 4TH AVE SUITE 100-461  
City: BRIGHTON State: CO Zip: 80601

**Findings:**

- 5 Number of Comments
- 3 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
BEAR STACY		stacy@strachanexploration.com	
Harms, Jason		Jason@strachanexploration.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
213042	WELL	PR	09/24/2007	OW	061-06403	WEINMAN 1-27	RI

**General Comment:**

This is a follow up of the previous reclamation inspections (#713600140, #713600430). Operator is directed to perform all outstanding corrective actions immediately.

**Location**

Overall Good:

**Signs/Marker:**

Type	WELLHEAD		
Comment:	The well sign is faded and does not meet the signage requirements. Previous corrective action is not completed.		
Corrective Action:	Install sign to comply with Rule 605.d.	Date:	
Type	BATTERY		
Comment:	There is no sign installed at the tank battery. Previous corrective action is not completed.		
Corrective Action:	Install sign to comply with Rule 605.e.	Date:	

**Emergency Contact Number:**

Comment:

Corrective Action:  Date: \_\_\_\_\_

Overall Good:

**Spills:**

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

**Fencing/:**

Type	TANK BATTERY		
Comment:	The fence around the tanks and production equipment is inadequate to prevent livestock entry and is not maintained. Previous corrective action is not completed.		
Corrective Action:	Comply with the fencing requirements per the 1002a rules.	Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
	3		STEEL AST		,
Comment:	<input type="text"/>				
Corrective Action:	<input type="text"/>				Date:

**Paint**

Condition	<input type="text"/>
Other (Content)	<input type="text"/>
Other (Capacity)	<input type="text"/>
Other (Type)	<input type="text"/>

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate			Adequate
Comment:	Earthen berms around the tank have been rebuilt.			
Corrective Action:	<input type="text"/>			
				Date:

**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type			
Comment:			
Corrective Action:		Date:	

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
713601026	Inspection Photos	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6550025">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6550025</a>