

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

05/16/2024

Submitted Date:

05/16/2024

Document Number:

716400109

FIELD INSPECTION FORM

Loc ID 317765 Inspector Name: Revas, Robbie On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 46290
Name of Operator: KP KAUFFMAN COMPANY INC
Address: 1700 LINCOLN ST STE 4550
City: DENVER State: CO Zip: 80203

Findings:

6 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
,		rwatzman@kpk.com	All Inspections
Silver, Randy		randy.silver@state.co.us	
Adamczyk, Megan		megan.adamczyk@state.co.us	complaint inspections
,		cogcc@kpk.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
239943	WELL	SI	11/01/2023	OW	123-07731	A L LUFT 1	SI

General Comment:

[This Field Inspection is due to a complaint Doc #403773135.](#)

Inspected Facilities

Facility ID: 239943 Type: WELL API Number: 123-07731 Status: SI Insp. Status: SI

Complaint

Comment: Inspection in response to complaint.
 Field Inspector Assigned: Robbie Revas
 Complaint Received
 Date: 5-13-2024
 Complaint Contacted: Yes via phone call.
 Date: 5-13-2024 Time: 11:50 AM
 Location ID: 317765
 Location name: A L Luft-61N67W 2NENW
 Well name: A L Luft 1
 API #05-123-07731
 Inspection Document # 716400105
 Complaint inspection document # 716400109
 Complaint Document form 18 # 403773135
 Nature of Complaint: Property Damage
 Field Inspector Actions:
 On 5-13-2024, I Robbie Revas area field inspector was assigned a complaint received by ECMC staff in reference to property damage. The complainant Patrick Hladky at 17977 C.R. 20 Fort Lupton, CO 80621 stated the issues were on the access road where the bridge crosses the irrigation ditch between the A L Luft 1 well & the A L Luft 2 well.
 On 5-15-24, I performed a complete site inspection of the well location.
 At time of inspection, I did write up compliance issues due to the bridge not being maintained, you can find them in my prior inspection document above on the ECMC website.
 Weather Conditions: sunny, cloudy with spotty light rain.
 Location Conditions: Mostly dry
 Violations of ECMC rules were observed at the time of the inspection.
 All information has been reviewed and site inspection information has been submitted to the ECMC for further review.

Corrective Action:

Date:

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment: _____

Corrective Action:

Date: _____

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

ECMC Comments

Comment	User	Date
Any Corrective Actions from previous inspections not addressed are still applicable.	revasr	05/16/2024