

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/10/2024

Submitted Date:

05/16/2024

Document Number:

694100363

**FIELD INSPECTION FORM**Loc ID 305680 Inspector Name: Robinson, Taylor On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**

ECMC Operator Number: 100322

Name of Operator: NOBLE ENERGY INC

Address: 2001 16TH STREET SUITE 900

City: DENVER State: CO Zip: 80202

**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

8 Number of Comments

3 Number of Corrective Actions

- ☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

| Contact Name | Phone | Email   | Comment              |
|--------------|-------|---|----------------------|
| ,            |       | NBL_DJBU_Inspections@NB<br>LENERGY.COM                | ALL INSPECTIONS      |
| ,            |       | rbucogccinspectionreports@c<br>hevron.onmicrosoft.com |                      |
| ,            |       | nbl_djbu_inspections@nblene<br>rgy.com                | ALL INSPECTIONS ONLY |

**General Comment:**

This is an environmental inspection for Location ID 305680 Blehm 26-8. Operator will note that the Loc ID in this case pertains to the wellhead while the inspection was for the Tank Battery. Any corrective actions from previous inspections that have not been addressed are still applicable. There were no operator or contract environmental personnel on location at the time of this field inspection. Photos attached to document site conditions.

**Location**Overall Good: ☐

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Good Housekeeping:**

Type

Comment: [Statewide unnecessary equipment, weeds, waste, and trash requirements](#)Corrective Action: [Comply with Rule 606](#)Date: [06/03/2024](#)Overall Good: ☐**Spills:**

Type

Area

Volume

In Containment: No

Comment: [No spills observed.](#)☐ Multiple Spills and Releases?**Tanks and Berms:**

| Contents           | # | Capacity | Type | Tank ID | SE GPS |       |
|--------------------|---|----------|------|---------|--------|-------|
|                    |   |          |      |         |        |       |
| Comment:           |   |          |      |         |        |       |
| Corrective Action: |   |          |      |         |        | Date: |

**Paint**

|                  |  |  |
|------------------|--|--|
| Condition        |  |  |
| Other (Content)  |  |  |
| Other (Capacity) |  |  |
| Other (Type)     |  |  |

**Berms**

| Type               | Capacity  | Permeability (Wall) | Permeability (Base) | Maintenance                      |
|--------------------|---|---------------------|---------------------|----------------------------------|
|                    |   |                     |                     |                                  |
| Comment:           | <a href="#">Dirt berms at the suspended storage tanks is wearing down (plastic under layer is exposed). Dirt berm around the separator is not sufficient.</a> |                     |                     |                                  |
|                    | <a href="#">Secondary containment is inadequate to contain 150% of the volume of the largest tank.</a>  |                     |                     |                                  |
| Corrective Action: | <a href="#">Repair or install berms or other secondary containment devices per Rule 603.o.</a>  |                     |                     | Date: <a href="#">06/13/2024</a> |

**Venting:**

|                    |  |       |
|--------------------|--|-------|
| Yes/No             |  |       |
| Comment:           |  |       |
| Corrective Action: |  | Date: |

**Flaring:**

|                    |  |       |
|--------------------|--|-------|
| Type               |  |       |
| Comment:           |  |       |
| Corrective Action: |  | Date: |

**Location Construction**

Location ID: 305680 CDP: \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**Form 2A COAs:****Comment:** \_\_\_\_\_

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**Wildlife BMPs:****Comment:** \_\_\_\_\_Corrective Action: \_\_\_\_\_ **Date:** \_\_\_\_\_**Comment:** Onsite rutting from vehicles observed. Needs to be smoothed out.**Corrective Action:** Install or repair required BMPs per Rule 1002.f.(2)C **Date:** 06/13/2024**On Site Inspection (305):****Surface Owner Contact Information:**

Name: \_\_\_\_\_ Address: \_\_\_\_\_

Phone Number: \_\_\_\_\_ Cell Phone: \_\_\_\_\_

**Operator Rep. Contact Information:**

Landman Name: \_\_\_\_\_ Phone Number: \_\_\_\_\_

Date Onsite Request Received: \_\_\_\_\_ Date of Rule 306 Consultation: \_\_\_\_\_

Request LGD Attendance: \_\_\_\_\_

**LGD Contact Information:**

Name: \_\_\_\_\_ Phone Number: \_\_\_\_\_ Agreed to Attend: \_\_\_\_\_

**Summary of Landowner Issues:**

|  |
|--|
|  |
|--|

**Summary of Operator Response to Landowner Issues:**

|  |
|--|
|  |
|--|

**Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:**

|  |
|--|
|  |
|--|

Environmental

Spills/Releases:

Type of Spill:Estimated Spill Volume:

Comment:

No spills or releases were observed at time of inspection.

Corrective Action:

Date:

Reportable:GPS: LatLong

Proximity to Surface Water:Depth to Ground Water:

Water Well Complaint:

DWR Receipt Num:Owner Name:GPS :

LatLong

Field Parameters:

Sample Location:

Comment:

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL   |
|--------------|-------------|---|
| 694100364    | photo log   | <a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6551067">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6551067</a> |