

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

05/09/2024

Submitted Date:

05/16/2024

Document Number:

708302159

**FIELD INSPECTION FORM**

Loc ID 335668 Inspector Name: Morris, Matthew On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

ECMC Operator Number: 10456  
Name of Operator: CAERUS PICEANCE LLC  
Address: 1001 17TH STREET #1600  
City: DENVER State: CO Zip: 80202

**Findings:**

- 9 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
, CAERUS		COGCC.inspections@caerusoilandgas.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
282873	WELL	PR	11/27/2006	GW	045-11864	N.PARACHUTE WF 12D K26 596	PR
282874	WELL	PR	11/29/2006	GW	045-11863	N.PARACHUTE WF 11B K26 596	PR
282875	WELL	PR	11/29/2006	GW	045-11862	N.PARACHUTE WF06D K26 596	PR
282878	WELL	PR	08/01/2019	GW	045-11861	N.PARACHUTE WFO5D K26 596	PR
282880	WELL	PR	11/29/2006	GW	045-11860	N.PARACHUTE WF 11D K26 596	PR
282881	WELL	PR	01/26/2006	GW	045-11859	N.PARACHUTE WF 9C-27 K26 59	PR
282882	WELL	PR	06/30/2008	GW	045-11858	N.PARACHUTE WF 16D-27 K25 5	PR
282883	WELL	PR	01/26/2006	GW	045-11857	N.PARACHUTE WF 13B K26 596	PR
292314	WELL	PR	01/01/2022	GW	045-14688	N. PARACHUTE WF02A-35 K26 59	PR
292315	WELL	PR	09/19/2007	GW	045-14687	N. PARACHUTE WF 13D K26 596	PR
292316	WELL	PR	04/01/2009	GW	045-14686	N. PARACHUTE WFO2C-35 K26 59	PR
292317	WELL	PR	03/20/2009	GW	045-14685	N. PARACHUTE WF 14A K26 596	PR
292318	WELL	PR	04/15/2009	GW	045-14684	N. PARACHUTE WF01D-35 K26 59	PR
292319	WELL	PR	03/20/2009	GW	045-14683	N. PARACHUTE WF14C K26 596	PR

292320	WELL	PR	04/15/2009	GW	045-14682	N. PARACHUTE WF08A-35 K26 59	PR
292321	WELL	PR	03/20/2009	GW	045-14681	N. PARACHUTE WFO7A- 35 K26 59	PR

**General Comment:**

COGCC Inspection Report Summary

On 5/9/2024 at approximately 12:45, Compliance Inspector Matthew Morris conducted an on-site inspection at CAERUS PICEANCE LLC, N.PARACHUTE-65S96W/26NESW at Location ID #335668 in Garfield County, Colorado.

Normal production operations were observed.

During the inspection, the following compliance issues were observed:

- 1) Debris

A follow-up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with CECMC rules.

This location is within or in close proximity to, a CPW Density/High Priority Habitat, Black Bear, NSO Habitat, or Wildlife Management area.

**Location**

Overall Good:

**Signs/Marker:**

Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	CONTAINERS		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:

Date:

**Good Housekeeping:**

Type	DEBRIS		
Comment:	Heater tubing debris on location.		
Corrective Action:	Remove debris to comply with Rule 606.	Date:	05/23/2024

Overall Good:

**Spills:**

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

**Fencing/:**

Type	WELLHEAD		
Comment:	Concrete barriers		
Corrective Action:		Date:	
Type	TANK BATTERY		
Comment:	Concrete barriers		
Corrective Action:		Date:	
Type	OTHER		
Comment:	Gas meters protected by concrete barriers		
Corrective Action:		Date:	

<b>Equipment:</b>			corrective date
Type: Bradenhead	# 16		
Comment:			
Corrective Action:			Date:
Type: Plunger Lift	# 16		
Comment:			
Corrective Action:			Date:
Type: Ancillary equipment	# 3		
Comment:	Chemical tanks		
Corrective Action:			Date:
Type: Gas Meter Run	# 20		
Comment:			
Corrective Action:			Date:
Type: Bird Protectors	# 1		
Comment:			
Corrective Action:			Date:
Type: Gas Meter Run	# 12		
Comment:			
Corrective Action:			Date:

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	200 BBLs	STEEL AST		
Comment:					
Corrective Action:					Date:

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

**Venting:**

Yes/No	NO	
Comment:		
Corrective Action:		Date:

**Flaring:**

Type	
------	--

Comment:		
Corrective Action:	Date:	

--

Inspected Facilities			
Facility ID: <u>282873</u>	Type: <u>WELL</u>	API Number: <u>045-11864</u>	Status: <u>PR</u> Insp. Status: <u>PR</u>
<b>Producing Well</b>			
Comment:			
Corrective Action:		Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12			
Facility ID: <u>282874</u>	Type: <u>WELL</u>	API Number: <u>045-11863</u>	Status: <u>PR</u> Insp. Status: <u>PR</u>
<b>Producing Well</b>			
Comment:			
Corrective Action:		Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12			
Facility ID: <u>282875</u>	Type: <u>WELL</u>	API Number: <u>045-11862</u>	Status: <u>PR</u> Insp. Status: <u>PR</u>
<b>Producing Well</b>			
Comment:			
Corrective Action:		Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12			
Facility ID: <u>282878</u>	Type: <u>WELL</u>	API Number: <u>045-11861</u>	Status: <u>PR</u> Insp. Status: <u>PR</u>
<b>Producing Well</b>			
Comment:			
Corrective Action:		Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12			
Facility ID: <u>282880</u>	Type: <u>WELL</u>	API Number: <u>045-11860</u>	Status: <u>PR</u> Insp. Status: <u>PR</u>
<b>Producing Well</b>			
Comment:			
Corrective Action:		Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12			
Facility ID: <u>282881</u>	Type: <u>WELL</u>	API Number: <u>045-11859</u>	Status: <u>PR</u> Insp. Status: <u>PR</u>
<b>Producing Well</b>			
Comment:			
Corrective Action:		Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12			
Facility ID: <u>282882</u>	Type: <u>WELL</u>	API Number: <u>045-11858</u>	Status: <u>PR</u> Insp. Status: <u>PR</u>
<b>Producing Well</b>			
Comment:			
Corrective Action:		Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12			
Facility ID: <u>282883</u>	Type: <u>WELL</u>	API Number: <u>045-11857</u>	Status: <u>PR</u> Insp. Status: <u>PR</u>
<b>Producing Well</b>			
Comment:			
Corrective Action:		Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12			

<b>Producing Well</b>			
Comment:			
Corrective Action:		Date:	

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 292314 Type: WELL API Number: 045-14688 Status: PR Insp. Status: PR

<b>Producing Well</b>			
Comment:			
Corrective Action:		Date:	

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 292315 Type: WELL API Number: 045-14687 Status: PR Insp. Status: PR

<b>Producing Well</b>			
Comment:			
Corrective Action:		Date:	

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 292316 Type: WELL API Number: 045-14686 Status: PR Insp. Status: PR

<b>Producing Well</b>			
Comment:			
Corrective Action:		Date:	

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 292317 Type: WELL API Number: 045-14685 Status: PR Insp. Status: PR

<b>Producing Well</b>			
Comment:			
Corrective Action:		Date:	

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 292318 Type: WELL API Number: 045-14684 Status: PR Insp. Status: PR

<b>Producing Well</b>			
Comment:			
Corrective Action:		Date:	

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 292319 Type: WELL API Number: 045-14683 Status: PR Insp. Status: PR

<b>Producing Well</b>			
Comment:			
Corrective Action:		Date:	

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 292320 Type: WELL API Number: 045-14682 Status: PR Insp. Status: PR

<b>Producing Well</b>			
Comment:			

Corrective Action:		Date:	
--------------------	--	-------	--

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID:	292321	Type:	WELL	API Number:	045-14681	Status:	PR	Insp. Status:	PR
--------------	--------	-------	------	-------------	-----------	---------	----	---------------	----

**Producing Well**

Comment:			
Corrective Action:		Date:	

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction						
		Check Dams				
		Gravel				
Gravel						
Seeding						
		Culverts				
				Material Handling And Spill Prevention		Chemical tank in secondary containment
		Ditches				
		Sediment Traps				
		Compaction				

Comment: Light gravel and compaction on location and lease road; future stormwater events may create tracking issues.

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
708302160	Photo Log	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6551387">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6551387</a>