

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/09/2024

Submitted Date:

05/10/2024

Document Number:

708903746

FIELD INSPECTION FORMLoc ID 334060 Inspector Name: Smelser, Wayne On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

ECMC Operator Number: 10456

Name of Operator: CAERUS PICEANCE LLC

Address: 1001 17TH STREET #1600

City: DENVER State: CO Zip: 80202

Status Summary:

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

27 Number of Comments

1 Number of Corrective Actions

- ☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Toews, Wesley		wtoews@blm.gov	
, Caerus		COGCC.inspections@caerus oilandgas.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
259547	WELL	PR	12/01/2021	GW	045-07740	S. PARACHUTE FEDERAL 30-42	PR
278634	WELL	PR	12/01/2021	GW	045-10900	FEDERAL 30-15BB (PN30)	PR
278635	WELL	PR	12/01/2021	GW	045-10899	FEDERAL 30-15 (PN30)	PR
278637	WELL	PR	12/01/2021	GW	045-10898	FEDERAL 30-11 (PN30)	PR
278672	WELL	PR	12/01/2021	GW	045-10915	FEDERAL 31-2BB (PN30)	PR

General Comment:**CECMC Inspection Report Summary**

On 05/09/2024 at approximately 13:11 hours, I, Compliance Specialist, Wayne Smelser
Conducted a follow up inspection at CAERUS PICEANCE LLC FEDERAL 30-15BB (PN30) Pad.
Location # 334060 in Garfield County Colorado.

Please refer to inspection 708902800 conducted on 01/17/2024, previous corrective actions have been completed.
Location is within High Priority/Density/Black Bear Habitat areas & in close proximity to NSO Habitat area.
Location is approximately 225 yards from Dry Creek.
While there, I observed normal production operations.

During this inspection the following compliance issues were observed:

1. Tanks & Berms - Suspected leaks on production tank/tank appears to lack integrity with a CA date of 05/17/2024

A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with CECMC rules.

This is a summary of inspection report.

Location**Lease Road:**

Type	Access		
comment:			
Corrective Action	L	Date:	

Overall Good: ☐**Signs/Marker:**

Type	OTHER		
Comment:	Sign at entrance to location		
Corrective Action:		Date:	
Type	OTHER		
Comment:	Separator units include attached storage tanks. The sight glass located on the side of the units indicates the storage tanks are full of an unknown fluid. No form of labeling or markers are present to identify a potential hazard or the contents of the storage tanks.		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment: 911/970-285-2615

Corrective Action:

Date: _____

Good Housekeeping:

Type	OTHER		
Comment:	Stained gravel in secondary containment		
Corrective Action:		Date:	
Type	DEBRIS		
Comment:	Debris - please refer to photo log		
Corrective Action:		Date:	

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?

Fencing/:			
Type	OTHER		
Comment:	Pig station & Summit Midstream meter house - bollards		
Corrective Action:		Date:	
Type	SEPARATOR		
Comment:	Cattle panels		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Cattle panels		
Corrective Action:		Date:	
Type	LOCATION		
Comment:	Barbed wire fence		
Corrective Action:		Date:	

Equipment:				corrective date
Type: Plunger Lift	# 5			
Comment:	All wells on plunger lift			
Corrective Action:		Date:		
Type: Gas Meter Run	# 5			
Comment:				
Corrective Action:		Date:		
Type: Pig Station	# 1			
Comment:				
Corrective Action:		Date:		
Type: Bradenhead	# 5			
Comment:	Pressure transducers located on all bradenhead. All bradenhead valves are accessible.			
Corrective Action:		Date:		
Type: Gas Meter Run	# 1			
Comment:	Summit Midstream			
Corrective Action:		Date:		
Type: Bird Protectors	# 1			
Comment:				
Corrective Action:		Date:		
Type: Vertical Heated Separator	# 5			
Comment:				
Corrective Action:		Date:		

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
METHANOL	1	1000 GAL	STEEL AST		,	
Comment:						
Corrective Action:					Date:	

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficent			
Comment:	Centralized containment				
Corrective Action:				Date:	
Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	3	300 BBLs	STEEL AST		
Comment:	Suspected leaks on production tank/tank appears to lack integrity (Tank # 81735)				
Corrective Action:	Contact environmental about suspected leak & provide proof that tank has integrity or repair tank.			Date:	05/17/2024

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficent		
Comment:	Centralized containment			
Corrective Action:				Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities								
Facility ID:	259547	Type:	WELL	API Number: 045-07740	Status:	PR	Insp. Status:	PR
Producing Well								
Comment:	Producing, well on plunger lift							
Corrective Action:						Date:		
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12								
Facility ID:	278634	Type:	WELL	API Number: 045-10900	Status:	PR	Insp. Status:	PR
Producing Well								
Comment:	Producing, well on plunger lift							
Corrective Action:						Date:		
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12								
Facility ID:	278635	Type:	WELL	API Number: 045-10899	Status:	PR	Insp. Status:	PR
Producing Well								
Comment:	Producing, well on plunger lift							
Corrective Action:						Date:		
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12								
Facility ID:	278637	Type:	WELL	API Number: 045-10898	Status:	PR	Insp. Status:	PR
Producing Well								
Comment:	Producing, well on plunger lift							
Corrective Action:						Date:		
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12								
Facility ID:	278672	Type:	WELL	API Number: 045-10915	Status:	PR	Insp. Status:	PR
Producing Well								
Comment:	Producing, well on plunger lift							
Corrective Action:						Date:		
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12								

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Gravel				Sparse to none in sections
		Ditches				
Gravel						Sparse to none in areas
		Compaction				Light compaction in some sections
		Culverts				
Compaction						Light compaction in areas

Comment: Places with sparse to no gravel & light compaction are present on location. Sparse/no gravel and light compaction could lead to future stabilization and tracking issues.

Corrective Action:

Date:

Pits: ☒ NO SURFACE INDICATION OF PIT

ECMC Comments

Comment	User	Date
Please refer to Tanks & Berms for observed compliance issue.	smelserw	05/10/2024

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403787371	INSPECTION SUBMITTED	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6544283
708903747	Inspection 708903746 Stormwater photo log	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6544281
708903748	Inspection 708903746 photo log	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6544282