

Inspection Photos

API: 061-06394

Operator: STRACHAN EXPLORATION INC

Inspection Date: 5/8/2024



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos



Photo 1. Facing east toward the offsite tank battery location.



Inspection Photos



Photo 2. The fence around the tank has been repaired but there is an opening at this area and there are only 2 wires which will not keep livestock out.



Inspection Photos



Photo 3. Facing northwest toward the wellsite. The fence around the pumpjack is in disrepair and wont prevent livestock entry.



Inspection Photos



Photo 4. Facing east toward the wellsite. There are parts laying on the ground that should be removed.



Inspection Photos



Photo 5. There is oily fluid in the containment next to the pump jack. Oily fluid has spilled onto the ground and needs to be cleaned up. Previous corrective action was not completed. Netting must be installed to prevent wildlife entry.

