

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/17/2024

Submitted Date:

05/17/2024

Document Number:

714201026

FIELD INSPECTION FORMLoc ID 427895 Inspector Name: Santistevan, Brittani On-Site Inspection ☐ 2A Doc Num: **Operator Information:**

ECMC Operator Number: 47120

Name of Operator: KERR MCGEE OIL & GAS ONSHORE LP

Address: P O BOX 173779

City: DENVER State: CO Zip: 80217-

Status Summary:

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

7 Number of Comments

1 Number of Corrective Actions

- ☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

| Contact Name | Phone | Email | Comment |
|--------------|-------|-------------------------|---------------------------------|
| , | | ECMCInspections@Oxy.com | All Inspections |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|------------------|-------------|
| 427881 | WELL | PR | 04/01/2022 | OW | 123-35149 | WEICHEL 14N-11HZ | PR |
| 427891 | WELL | PR | 04/01/2022 | OW | 123-35158 | WEICHEL 28N-11HZ | PR |

General Comment:[THIS IS A FOLLOW UP INSPECTION.](#)

| | | | |
|--|--------|---|--|
| Location | | | |
| Overall Good: <input checked="" type="checkbox"/> | | | |
| Emergency Contact Number: | | | |
| Comment: | | | |
| Corrective Action: | | Date: _____ | |
| Good Housekeeping: | | | |
| Type | DEBRIS | | |
| Comment: | | debris/weeds on various areas of location. See attached photos. | |
| Corrective Action: | | Comply with Rule 606. | |
| | | Date: 05/31/2024 | |
| Overall Good: <input type="checkbox"/> | | | |
| Spills: | | | |
| Type | Area | Volume | |
| In Containment: No | | | |
| Comment: | | | |
| <input type="checkbox"/> Multiple Spills and Releases? | | | |
| Equipment: | | corrective date | |
| Type: Other | # | | |
| Comment: | | It appears all equipment remains the same as stated in previous DOC#: 714200321 | |
| Corrective Action: | | Date: | |
| Venting: | | | |
| Yes/No | NO | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Flaring: | | | |
| Type | | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

| Inspected Facilities | | | | | | | | | |
|--|--|-------|------|-------------|-----------|---------|----|---------------|----|
| Facility ID: | 427881 | Type: | WELL | API Number: | 123-35149 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | PR; it appears valves are in an open position. | | | | | | | | |
| Corrective Action: | | | | | | Date: | | | |
| The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12 | | | | | | | | | |
| Facility ID: | 427891 | Type: | WELL | API Number: | 123-35158 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | PR; it appears valves are in an open position. | | | | | | | | |
| Corrective Action: | | | | | | Date: | | | |
| The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12 | | | | | | | | | |
| | | | | | | | | | |

Reclamation - Storm Water - Pit

Storm Water:

| | | | | | | |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
| Gravel | | Gravel | | | | |

Comment:

Corrective Action:

Date:

Pits: ☐ NO SURFACE INDICATION OF PIT

ECMC Comments

| Comment | User | Date |
|---|----------|------------|
| <p>THIS IS A FOLLOW UP INSPECTION TO PREVIOUS INSPECTION DOC#: 714200321. All previous corrective actions assigned to this location appear to have been resolved. One new corrective action was observed at the time of re-inspection. Review form below for additional information.</p> <p>ECMC Inspection Report Summary WEATHER CONDITIONS: sunny, dry ground On Friday, May 17, 2024 at approximately 1030, I, Inspector Brittani Santistevan, conducted an on-site inspection at WEICHEL 14N, 28N-11HZ, (Kerr McGee Oil & Gas Onshore), at location ID: 427895 in WELD COUNTY, Colorado. While there, I observed a producing facility. During this inspection the following possible compliance issues were observed: 1. It appears to be debris/weds on various areas of location. Comply with Rule 606. (corrective Action Date: May 31, 2024) See attached photo #5, 7, 8, 11.</p> <p>A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.</p> | santistb | 05/17/2024 |

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|-------------|---|
| 714201027 | Photos | https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6552203 |