

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC SPRUCE CREEK PRODUCTION PIT 14-4-794

Location #: 427810



Photo # 6797 From entrance to location



Photo # 6798 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC SPRUCE CREEK PRODUCTION PIT 14-4-794

Location #: 427810



Photo # 6799 Location



Photo # 6800 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC SPRUCE CREEK PRODUCTION PIT 14-4-794

Location #: 427810



May 13, 2024 at 2:21:18 PM
CO

Photo # 6801 Location



May 13, 2024 at 2:30:52 PM
CO

Photo # 6802 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC SPRUCE CREEK PRODUCTION PIT 14-4-794

Location #: 427810



Photo # 6803 Location



Photo # 6804 Unused equipment

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC SPRUCE CREEK PRODUCTION PIT 14-4-794

Location #: 427810



**Photo # 6805 Open ended piping on unused equipment
/wildlife hazard/available for entry by wildlife**



**Photo # 6806 Turbine not properly installed on unused
equipment/wildlife hazard/available for entry by wildlife**

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC SPRUCE CREEK PRODUCTION PIT 14-4-794

Location #: 427810



May 13, 2024 at 2:16:37 PM
CO

Photo # 6807 Possible nest inside turbine on unused equipment



May 13, 2024 at 2:28:07 PM
CO

Photo # 6808 Barbed wire laying on ground/wildlife hazard (SW corner of location on top of cut slope)

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC SPRUCE CREEK PRODUCTION PIT 14-4-794

Location #: 427810



**Photo # 6809 Barbed wire laying on ground/wildlife hazard
(SW corner of location on top of cut slope)**



**Photo # 6810 Barbed wire laying on ground/wildlife hazard
(SW corner of location on top of cut slope)**

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC SPRUCE CREEK PRODUCTION PIT 14-4-794

Location #: 427810



**Photo # 6811 Barbed wire laying on ground/wildlife hazard
(SW corner of location on top of cut slope)**



**Photo # 6812 Barbed wire laying on ground/wildlife hazard
(SW corner of location on top of cut slope)**

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC SPRUCE CREEK PRODUCTION PIT 14-4-794

Location #: 427810



Photo # 6813 Debris



Photo # 6814 Debris

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC SPRUCE CREEK PRODUCTION PIT 14-4-794

Location #: 427810



Photo # 6815 Debris



Photo # 6816 Debris