

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/16/2024

Submitted Date:

05/20/2024

Document Number:

708903827**FIELD INSPECTION FORM**Loc ID 311595 Inspector Name: Smelser, Wayne On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**ECMC Operator Number: 10550Name of Operator: MUSTANG RESOURCES LLCAddress: PO BOX 13550City: BAKERSFIELD State: CA Zip: 93389**Status Summary:**

- ☐
- THIS IS A FOLLOW UP INSPECTION
-
- ☐
- FOLLOW UP INSPECTION REQUIRED
-
- ☒
- NO FOLLOW UP INSPECTION REQUIRED

Findings:15 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
, Mustang		nwelch@vaqueroenergy.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
258989	WELL	PR	10/01/2023	GW	045-07677	SAVAGE 9-26-6-94 W	PR

General Comment:**CECMC Inspection Report Summary**

On 05/16/2024 at approximately 15:10 hours, I, Compliance Specialist, Wayne Smelser
 Conducted an on-site inspection at MUSTANG RESOURCES LLC SAVAGE9-26-6-94 W Pad.
 Location # 311595 in Garfield County Colorado.
 Location is within High Priority/Density/Black Bear Habitat areas.
 While there, I observed normal production operations.

This is a summary of inspection report.

Dual lease - Shared facilities with the JUHAN ASTRAL FED FEE 1-26-6S-94W pad, location # 311532
 Please refer to inspection 708903824 for corrective actions

Location

Lease Road:			
Type	Access		
comment:			
Corrective Action	L	Date:	

Overall Good: ☐

Signs/Marker:			
Type	WELLHEAD		
Comment:	Sign bent		
Corrective Action:		Date:	
Type	BATTERY		
Comment:	No tank battery on location		
Corrective Action:		Date:	

Emergency Contact Number:			
Comment:	911/1-888-291-8588		
Corrective Action:			Date: _____

Good Housekeeping:			
Type	OTHER		
Comment:	Wellhead cellar lacks wildlife egress - Please refer to inspection 708903824 for corrective action		
Corrective Action:			Date:
Type	DEBRIS		
Comment:	Large amount of pipe laying near location		
Corrective Action:			Date:

Overall Good: ☐

Spills:			
Type	Area	Volume	

In Containment: No

Comment: ☐ Multiple Spills and Releases?

Fencing/:			
Type	WELLHEAD		
Comment:	Pipe rail fence		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Plunger Lift	# 0		
Comment:	Well not on plunger lift		
Corrective Action:			Date:
Type: Gas Meter Run	# 0		
Comment:	Meter house located on the JUHAN ASTRAL FED FEE 1-26-6S-94W pad, location # 311532		

Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:	No form of pressure monitoring equipment located on bradenheads. All bradenhead valves are accessible.		
Corrective Action:		Date:	
<u>Venting:</u>			
Yes/No	NO		
Comment:			
Corrective Action:		Date:	
<u>Flaring:</u>			
Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities									
Facility ID:	258989	Type:	WELL	API Number:	045-07677	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing, well not on plunger lift								
Corrective Action:				Date:					

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Ditches				
		Gravel				Sparse to none in most sections
Gravel						Sparse to none
		Rip Rap				
Compaction						
		Culverts				
		Compaction				Light compaction in some areas

Comment:

Corrective Action:

Date:

Pits: ☒ NO SURFACE INDICATION OF PIT

ECMC Comments

Comment	User	Date
Dual lease - Shared facilities with the JUHAN ASTRAL FED FEE 1-26-6S-94W pad, location # 311532	smelserw	05/20/2024
Please refer to inspection 708903824 for corrective actions		

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
708903828	Inspection 708903827 photo log	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6554419
708903829	Inspection 708903827 Stormwater photo log	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6554420