

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

05/20/2024

Submitted Date:

05/20/2024

Document Number:

714201039

FIELD INSPECTION FORM

Loc ID 332730 Inspector Name: Santistevan, Brittani On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 10633
Name of Operator: CRESTONE PEAK RESOURCES OPERATING LLC
Address: 555 17TH STREET SUITE 3700
City: DENVER State: CO Zip: 80202

Findings:

- 5 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
,		Inspections@civiresources.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
241541	WELL	SI	12/01/2023	GW	123-09330	ARISTOCRAT ANGUS 21-4	SI
248772	WELL	SI	08/01/2023	OW	123-16574	ARISTOCRAT ANGUS 21-4C	PA

General Comment:

[THIS IS A FOLLOW UP INSPECTION.](#)

Inspected Facilities

Facility ID: 241541 Type: WELL API Number: 123-09330 Status: SI Insp. Status: SI

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: EQUIPMENT ONSITE

Comment: SAI; previous inspection .

Corrective Action: Date:

BradenHead

Date of Last Brhd Test: 01/23/2024 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type:

End Surf Csg Pressure: 0

Comment:

Corrective Action: Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 248772 Type: WELL API Number: 123-16574 Status: SI Insp. Status: PA

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: PREVIOUS INSPECTION

Comment: PA

Corrective Action: Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

ECMC Comments

Comment	User	Date
THIS IS A FOLLOW UP INSPECTION TO PREVIOUS INSPECTION DOC#:714200859 AND IN REPOSE TO FIRR DOC#: 403742226. It appears all previous corrective actions assigned to this location have been resolved. For additional information please refer to previous inspection DOC#: 714200859 or FIRR DOC#: 403742226	santistb	05/20/2024