

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

05/20/2024

Submitted Date:

05/20/2024

Document Number:

713300917

FIELD INSPECTION FORM

Loc ID 305802 Inspector Name: Kester, Michael On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 100322
Name of Operator: NOBLE ENERGY INC
Address: 1099 18TH STREET SUITE 1500
City: DENVER State: CO Zip: 80202

Findings:

- 7 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Gomez, Jason		jason.gomez@state.co.us	
,		rbucogccinspectionreports@chevron.onmicrosoft.com	
Peterson, Tom		tom.peterson@state.co.us	
Kraich, Adam		adam.kraich@state.co.us	
Leonard, Mike		mike.leonard@state.co.us	
Silver, Randy	720-827-6688	randy.silver@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
282496	WELL	SI	07/01/2020	GW	123-23501	BOOS 20-25	SI

General Comment:

[accident report](#)

Location

Overall Good:

Signs/Marker:

	Type WELLHEAD		
Comment:	good		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:
 Corrective Action: Date: _____

Overall Good:

Spills:

Type	Area	Volume			

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

	Type WELLHEAD		
Comment:	metal panels		
Corrective Action:		Date:	

Equipment:

		# 1			corrective date
Type: Ancillary equipment					
Comment:	automation panels				
Corrective Action:				Date:	
Type: Plunger Lift		# 1			
Comment:					
Corrective Action:				Date:	
Type: Bradenhead		# 1			
Comment:	piped to surface				
Corrective Action:				Date:	

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 282496 Type: WELL API Number: 123-23501 Status: SI Insp. Status: SI

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____
 Comment: Form 6A on file, 8-17-2022
 Corrective Action: _____ Date: _____

BradenHead

Date of Last Brhd Test: 03/07/2024 Annual Brhd Completed? Yes
 Last Brhd Test Results Initial Surf Csg Pressure: 41 Fluid Type: WATER H2O
 End Surf Csg Pressure: 0
 Comment: _____
 Corrective Action: _____ Date: _____

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

ECMC Comments

Comment	User	Date
<p>ECMC Inspection Report Summary Inspector Michael Kester, Location: Boos 20-25 Operator: Noble Energy API#: 123-23501 County: Weld</p> <p>5-18-2024 8:00pm Received Platteville/Gilcrest Fire Protection Evacuation Notice, natural gas wellhead was struck spewing gas into air. Spoke with my supervisor then travel to site to investigate and discover well exact API, location and details of accident. Chevron operator and Fire and Rescue on site, wind blowing from Southeast towards agriculture field open area. Details of agriculture spraying equipment struck shut in wellhead breaking master valve, lubricator and other associated connected piping. Pressure appeared to decrease @ 10:00pm, Fire and Rescue released @ 10:30, Chevron personnel on site to monitor well condition until morning light.</p> <p>5-19-2024 8:00am at time inspection, well was actively under pressure, same as last 10 hrs, Chevron Air Team with monitors and Drone Team on site taking pictures, actively monitor site condition. Well control team working on plans to secure well, 2 transport truck and trailer with water staged. Chevron personnel standby on site monitor well condition thru night.</p> <p>5-20-2024 7:00am at time of inspection, well appeared to have no preseure , well head does not appeared secured, Form 6A on file 8-17-2022 with plugging scheduled, Walked wellhead area, took pictures, slight petroleum odor. 10:00am rig and equipment arriving on site to secure well and P&A.</p> <p>Weather conditions: over cast and dry This inspection does not nullify any orders or NOAV from the ECMC This is a continuing education inspection</p>	kesterm	05/20/2024

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
713300918	site pic, 19th & 20th of May 2024	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6555313