

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/16/2024

Submitted Date:

05/20/2024

Document Number:

708903833

**FIELD INSPECTION FORM**

Loc ID 335488	Inspector Name: Smelser, Wayne	On-Site Inspection <input type="checkbox"/>	2A Doc Num: _____	<b>Status Summary:</b> <input type="checkbox"/> THIS IS A FOLLOW UP INSPECTION <input type="checkbox"/> FOLLOW UP INSPECTION REQUIRED <input checked="" type="checkbox"/> NO FOLLOW UP INSPECTION REQUIRED  <b>Findings:</b> 32 Number of Comments 0 Number of Corrective Actions <input type="checkbox"/> Corrective Action Response Requested
<b>Operator Information:</b> ECMC Operator Number: 96850 Name of Operator: TEP ROCKY MOUNTAIN LLC Address: 1058 COUNTY ROAD 215 City: PARACHUTE State: CO Zip: 81635				<b>ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE</b>

**Contact Information:**

Contact Name	Phone	Email	Comment
, TEP		COGCCInspectionReports@terraep.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
298067	WELL	PR	01/31/2010	GW	045-17050	SAVAGE RWF 544-26	PR
298068	WELL	PR	02/26/2009	GW	045-17052	SAVAGE RWF 543-26	PR
298069	WELL	PR	12/31/2009	GW	045-17053	SAVAGE RWF 343-26	PR
298070	WELL	PR	12/31/2009	GW	045-17054	SAVAGE RWF 43-26	PR
298071	WELL	PR	01/31/2010	GW	045-17055	SAVAGE RWF 434-26	PR
298072	WELL	PR	01/31/2010	GW	045-17056	SAVAGE RWF 34-26	PR
298073	WELL	PR	01/31/2010	GW	045-17057	SAVAGE RWF 533-26	PR
298074	WELL	PR	12/31/2009	GW	045-17058	SAVAGE RMV 47-26	PR
298075	WELL	PR	01/11/2010	GW	045-17059	SAVAGE RWF 433-26	PR
298076	WELL	PR	01/31/2010	GW	045-17060	SAVAGE RWF 344-26	PR
298077	WELL	PR	10/01/2023	GW	045-17061	SAVAGE RWF 44-26	PR

**General Comment:**

CECMC Inspection Report Summary

On 05/16/2024 at approximately 15:18 hours, I, Compliance Specialist, Wayne Smelser  
 Conducted an on-site inspection at TEP ROCKY MOUNTAIN LLC SAVAGE RWF34-26 Pad.  
 Location # 335488 in Garfield County Colorado.  
 Location is within High Priority/Density/Black Bear Habitat areas.  
 While there, I observed normal production operations.

This is a summary of inspection report.

**Location****Lease Road:**

Type	Access		
comment:			
Corrective Action:		Date:	

Overall Good: ☐**Signs/Marker:**

Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	OTHER		
Comment:	Separator units include attached storage tanks. The sight glass located on the side of the units indicates the storage tanks are full of an unknown fluid. No form of labeling or markers are present to identify a potential hazard or the contents of the storage tanks.		
Corrective Action:		Date:	
Type	CONTAINERS		
Comment:	Chemical tanks		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment: 911/970-285-9377

Corrective Action:

Date: \_\_\_\_\_

**Good Housekeeping:**

Type	DEBRIS		
Comment:	Dead weeds/debris - please refer to photo log		
Corrective Action:		Date:	
Type	OTHER		
Comment:	Staining near 3-4 wellheads		
Corrective Action:		Date:	

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?

<b>Fencing/:</b>			
Type	SEPARATOR		
Comment:	Hog panels		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Hog panels		
Corrective Action:		Date:	
Type	OTHER		
Comment:	Chemical tanks & liquid nitrogen tank - hog panels		
Corrective Action:		Date:	
Type	TANK BATTERY		
Comment:	Hog panels		
Corrective Action:		Date:	
<b>Equipment:</b>			corrective date
Type: Ancillary equipment	# 2		
Comment:	Chemical tanks		
Corrective Action:		Date:	
Type: Bird Protectors	# 7		
Comment:			
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 11		
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	Liquid nitrogen tank		
Corrective Action:		Date:	
Type: Plunger Lift	# 11		
Comment:	All wells on plunger lift		
Corrective Action:		Date:	
Type: Bradenhead	# 11		
Comment:	Taylor plugs located on all bradenhead. All bradenhead valves are accessible.		
Corrective Action:		Date:	
Type: Gas Meter Run	# 11		
Comment:			
Corrective Action:		Date:	
Type: Deadman # & Marked	# 10		
Comment:	9 marked deadman & 1 unmarked deadman  All guy line anchors left buried for future use will be identified by a marker of bright color not less than 4 feet in height and not greater than 1 foot east of the guy line anchor.		
Corrective Action:		Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	1	<100 BBLs	STEEL AST		,	
Comment: Tank equipped with telemetry						
Corrective Action:					Date:	

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)	80 bbl	
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient		
Comment:				
Corrective Action:				Date:

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities				
Facility ID:	298067	Type:	WELL	API Number: 045-17050 Status: PR Insp. Status: PR
<b>Producing Well</b>				
Comment:	Producing, well on plunger lift			
Corrective Action:		Date:		
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				
Facility ID:	298068	Type:	WELL	API Number: 045-17052 Status: PR Insp. Status: PR
<b>Producing Well</b>				
Comment:	Producing, well on plunger lift			
Corrective Action:		Date:		
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				
Facility ID:	298069	Type:	WELL	API Number: 045-17053 Status: PR Insp. Status: PR
<b>Producing Well</b>				
Comment:	Producing, well on plunger lift			
Corrective Action:		Date:		
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				
Facility ID:	298070	Type:	WELL	API Number: 045-17054 Status: PR Insp. Status: PR
<b>Producing Well</b>				
Comment:	Producing, well on plunger lift			
Corrective Action:		Date:		
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				
Facility ID:	298071	Type:	WELL	API Number: 045-17055 Status: PR Insp. Status: PR
<b>Producing Well</b>				
Comment:	Producing, well on plunger lift			
Corrective Action:		Date:		
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				
Facility ID:	298072	Type:	WELL	API Number: 045-17056 Status: PR Insp. Status: PR
<b>Producing Well</b>				
Comment:	Producing, well on plunger lift			
Corrective Action:		Date:		
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				
Facility ID:	298073	Type:	WELL	API Number: 045-17057 Status: PR Insp. Status: PR
<b>Producing Well</b>				
Comment:	Producing, well on plunger lift			
Corrective Action:		Date:		
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				
Facility ID:	298074	Type:	WELL	API Number: 045-17058 Status: PR Insp. Status: PR
<b>Producing Well</b>				
Comment:	Producing, well on plunger lift			
Corrective Action:		Date:		
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				

<b>Producing Well</b>			
Comment:	Producing, well on plunger lift		
Corrective Action:		Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12			
Facility ID:	298075	Type:	WELL
API Number:	045-17059	Status:	PR
Insp. Status:	PR		
<b>Producing Well</b>			
Comment:	Producing, well on plunger lift		
Corrective Action:		Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12			
Facility ID:	298076	Type:	WELL
API Number:	045-17060	Status:	PR
Insp. Status:	PR		
<b>Producing Well</b>			
Comment:	Producing, well on plunger lift		
Corrective Action:		Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12			
Facility ID:	298077	Type:	WELL
API Number:	045-17061	Status:	PR
Insp. Status:	PR		
<b>Producing Well</b>			
Comment:	Producing, well on plunger lift		
Corrective Action:		Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12			

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Ditches				
Gravel						Sparse to none in most areas
		Compaction				
		Culverts				
		Gravel				Sparse to none in sections
				Material Handling And Spill Prevention		Chemical tank containments
		Rip Rap				
Compaction						Small areas of light compaction

Comment:

Corrective Action:

Date:

Pits: ☒ NO SURFACE INDICATION OF PIT

ECMC Comments

Comment	User	Date
Please refer to Housekeeping & Equipment for comments	smelserw	05/20/2024

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
708903834	Inspection 708903833 Stormwater photo log	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6555479">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6555479</a>
708903835	Inspection 708903833 photo log	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6555480">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6555480</a>