

State of Colorado
Energy & Carbon Management Commission



1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Document Number:

403798165

Date Received:

05/21/2024

FIR RESOLUTION FORM

Overall Status:

CA Summary:

1 of 1 CAs from the FIR responded to on this Form

0 CA Completed

1 Factual Review Request

OPERATOR INFORMATION

ECMC Operator Number: 47120

Name of Operator: KERR MCGEE OIL & GAS ONSHORE LP

Address: 501 N DIVISION BLVD

City: PLATTEVILLE State: CO Zip: 80651

Contact Name and Telephone:

Name: _____

Phone: () Fax: ()

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

Stormo, Drew

drew_stormo@oxy.com

Lee, Austin

austin_lee@oxy.com

COGCCInspections@Oxy.com

ECMC INSPECTION SUMMARY:

FIR Document Number: 713900603

Inspection Date: 05/07/2024

FIR Submit Date: 05/16/2024

FIR Status: _____

Inspected Operator Information:

Company Name: KERR MCGEE OIL & GAS ONSHORE LP

Company Number: 47120

Address: P O BOX 173779

City: DENVER State: CO Zip: 80217-3779

LOCATION - Location ID: 336371

Location Name: NESG-63N68W Number: 24SWSW County: _____

Qtrqtr: SWS Sec: 24 Twp: 3N Range: 68W Meridian: 6

W

Latitude: 40.207520 Longitude: -104.957630

FACILITY - API Number: 05-123- -00 Facility ID: 336371

Facility Name: NESG-63N68W Number: 24SWSW

Qtrqtr: SWS Sec: 24 Twp: 3N Range: 68W Meridian: 6

W

Latitude: 40.207520 Longitude: -104.957630

CORRECTIVE ACTIONS:

1 CA# 195245

Corrective Action: Comply with the reclamation rules to remove all debris, abandoned gathering line risers, and flowline risers, and equipment (regardless of ownership) within three months of plugging (9/30/2021) the associated facility. All work should have been conducted by 12/30/2021.

Date: 06/16/2024

Response:	<u>FACTUAL REVIEW REQUEST</u>
Basis for Review:	<u>Equipment is not owned or controlled by the operator</u>
Operator Comment:	<div>Operator reached out to Western Midstream to determine whether the equipment was abandoned or active. Western Midstream said the riser was tied to active gathering lines and are currently in use.</div>
ECMC Decision:	<div></div>
ECMC Representative:	<div></div>

<u>OPERATOR COMMENT AND SUBMITTAL</u>	
Comment:	<div>Please route to area reclamation specialist, operator reached out to midstream company who acknowledged that risers are tied to active lines and remain in use.</div>
I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.	
Print Name:	<u>Drew Stormo</u>
Signed:	<div></div>
Title:	<u>Advisor HSE Environ Ops</u>
Date:	<u>5/21/2024 9:33:32 AM</u>

ATTACHMENT LIST

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>

Total Attach: 0 Files