

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

05/21/2024

Submitted Date:

05/21/2024

Document Number:

713300920

FIELD INSPECTION FORM

Loc ID 305802 Inspector Name: Kester, Michael On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 100322
Name of Operator: NOBLE ENERGY INC
Address: 1099 18TH STREET SUITE 1500
City: DENVER State: CO Zip: 80202

Findings:

8 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Peterson, Tom		tom.peterson@state.co.us	
Gomez, Jason		jason.gomez@state.co.us	
Kraich, Adam		adam.kraich@state.co.us	
Leonard, Mike		mike.leonard@state.co.us	
,		rbucogccinspectionreports@chevron.onmicrosoft.com	All Inspections
Silver, Randy	720-827-6688	randy.silver@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
282496	WELL	SI	07/01/2020	GW	123-23501	BOOS 20-25	SI

General Comment:

[Rig inspection](#)

Location

Overall Good:

Signs/Marker:

	Type WELLHEAD		
	Comment: good		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:	<input style="width: 95%;" type="text"/>		
Corrective Action:	<input style="width: 95%;" type="text"/>	Date:	<input style="width: 80%;" type="text"/>

Overall Good:

Spills:

Type	Area	Volume			

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

	Type WELLHEAD		
	Comment: metal panels, removed		
Corrective Action:		Date:	

Equipment:

Type:	#				corrective date
Comment:					
Corrective Action:			Date:		
Type: Ancillary equipment	# 1				
Comment: automation removed					
Corrective Action:			Date:		
Type: Bradenhead	# 1				
Comment: pipe to surface					
Corrective Action:			Date:		

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 282496 Type: WELL API Number: 123-23501 Status: SI Insp. Status: SI

BradenHead

Date of Last Brhd Test: 03/07/2024 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 41 Fluid Type: WATER H2O
 End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date: _____

Workover

Comment:

Corrective Action:

Date: _____

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

ECMC Comments

Comment	User	Date
<p>ECMC Inspection Report Summary Inspector Michael Kester, conducted on-site inspection Location: Boos 20-25 Operator: Noble Energy API#: 123-23501 County: Weld</p> <p>5-21-2024, Chevron crews fencing release area, Rig crew standby on wireline, to start tripping out tubing form 6A on file 8-17-22</p> <p>form 19, discovery form 22, accident form 42, MIRU form 42, P&A on file 5-19-24</p> <p>Weather conditions: sunny and dry This is a summary of inspection report.</p> <p>This inspection does not nullify any orders or NOAV from the ECMC This is a continuing education inspection</p>	kesterm	05/21/2024

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
713300921	site pic	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6555936