

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

05/15/2024

Submitted Date:

05/21/2024

Document Number:

709700391

**FIELD INSPECTION FORM**

Loc ID: 319699 Inspector Name: Huck, Keith On-Site Inspection:  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

ECMC Operator Number: 46290  
Name of Operator: KP KAUFFMAN COMPANY INC  
Address: 1700 LINCOLN ST STE 4550  
City: DENVER State: CO Zip: 80203

**Findings:**

8 Number of Comments  
0 Number of Corrective Actions  
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

| Contact Name | Phone | Email         | Comment                         |
|--------------|-------|---------------|---------------------------------|
|              |       | cogcc@kpk.com | <a href="#">All Inspections</a> |

**Inspected Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num   | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|---------------|-------------|
| 201001      | WELL | PR     | 01/01/2023  | OW         | 001-06404 | HAUGEN 1-30   | PR          |

**General Comment:**

Empty text area for general comments.

**Location**

Overall Good:

**Signs/Marker:**

|                    |                      |       |  |
|--------------------|----------------------|-------|--|
| Type               | WELLHEAD             |       |  |
| Comment:           | Adequate             |       |  |
| Corrective Action: |                      | Date: |  |
| Type               | BATTERY              |       |  |
| Comment:           | Adequate             |       |  |
| Corrective Action: |                      | Date: |  |
| Type               | TANK LABELS/PLACARDS |       |  |
| Comment:           | Adequate             |       |  |
| Corrective Action: |                      | Date: |  |

Emergency Contact Number:

Comment: Adequate

Corrective Action:

Date: \_\_\_\_\_

Overall Good:

**Spills:**

| Type | Area | Volume |  |  |
|------|------|--------|--|--|
|      |      |        |  |  |

In Containment: No

Comment:

Multiple Spills and Releases?

**Equipment:**

| Type                          |          |       | corrective date |
|-------------------------------|----------|-------|-----------------|
| Type: Bird Protectors         | # 3      |       |                 |
| Comment:                      |          |       |                 |
| Corrective Action:            |          | Date: |                 |
| Type: Gas Meter Run           | # 1      |       |                 |
| Comment:                      |          |       |                 |
| Corrective Action:            |          | Date: |                 |
| Type: Pump Jack               | # 1      |       |                 |
| Comment:                      |          |       |                 |
| Corrective Action:            |          | Date: |                 |
| Type: Emission Control Device | # 2      |       |                 |
| Comment:                      |          |       |                 |
| Corrective Action:            |          | Date: |                 |
| Type: Deadman # & Marked      | # 4      |       |                 |
| Comment:                      |          |       |                 |
| Corrective Action:            |          | Date: |                 |
| Type: Ancillary equipment     | # 1      |       |                 |
| Comment:                      | Auto RTU |       |                 |

|                                   |                                  |       |  |
|-----------------------------------|----------------------------------|-------|--|
| Corrective Action:                |                                  | Date: |  |
| Type: Bradenhead                  | # 1                              |       |  |
| Comment:                          | Appears to be plumbed to surface |       |  |
| Corrective Action:                |                                  | Date: |  |
| Type: Horizontal Heated Separator | # 1                              |       |  |
| Comment:                          |                                  |       |  |
| Corrective Action:                |                                  | Date: |  |

**Tanks and Berms:**

| Contents           | # | Capacity | Type      | Tank ID | SE GPS                |
|--------------------|---|----------|-----------|---------|-----------------------|
| CRUDE OIL          | 1 | 400 BBLs | STEEL AST |         | 39.849922,-104.260162 |
| Comment:           |   |          |           |         |                       |
| Corrective Action: |   |          |           |         | Date:                 |

**Paint**

|                  |          |
|------------------|----------|
| Condition        | Adequate |
| Other (Content)  |          |
| Other (Capacity) |          |
| Other (Type)     |          |

**Berms**

| Type               | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
|--------------------|----------|---------------------|---------------------|-------------|
| Earth              | Adequate | Walls Sufficient    | Base Sufficient     | Adequate    |
| Comment:           |          |                     |                     |             |
| Corrective Action: |          |                     |                     | Date:       |

| Contents           | # | Capacity | Type                | Tank ID | SE GPS |
|--------------------|---|----------|---------------------|---------|--------|
| PRODUCED WATER     | 1 | <50 BBLs | CONCRETE SUMP/VAULT |         | ,      |
| Comment:           |   |          |                     |         |        |
| Corrective Action: |   |          |                     |         | Date:  |

**Paint**

|                  |  |
|------------------|--|
| Condition        |  |
| Other (Content)  |  |
| Other (Capacity) |  |
| Other (Type)     |  |

**Berms**

| Type               | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
|--------------------|----------|---------------------|---------------------|-------------|
| Earth              | Adequate | Walls Sufficient    | Base Sufficient     | Adequate    |
| Comment:           |          |                     |                     |             |
| Corrective Action: |          |                     |                     | Date:       |

**Wells Served By Facilities Above**

|            |
|------------|
| API Number |
| 001-06404  |

**AirsID**

|            |        |
|------------|--------|
| API Number | AirsID |
|------------|--------|

**Venting:**

|                    |    |       |  |
|--------------------|----|-------|--|
| Yes/No             | NO |       |  |
| Comment:           |    |       |  |
| Corrective Action: |    | Date: |  |

**Flaring:**

|                    |  |       |  |
|--------------------|--|-------|--|
| Type               |  |       |  |
| Comment:           |  |       |  |
| Corrective Action: |  | Date: |  |

**Inspected Facilities**

Facility ID: 201001 Type: WELL API Number: 001-06404 Status: PR Insp. Status: PR

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: EQUIPMENT ONSITE

Comment: SI

Corrective Action:  Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

| Document Num | Description       | URL   |
|--------------|-------------------|---|
| 709700392    | Inspection Photos | <a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6556102">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6556102</a> |