

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, BORUCH-67S96W/11NESE

Location ID: 334984

Date: 5/16/2024



Wellheads – Photo #01249



Separators – Photo #01258

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, BORUCH-67S96W/11NESE

Location ID: 334984

Date: 5/16/2024



Tank Battery – Photo #01255



Open-Ended Load Line – Photo #01256

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, BORUCH-67S96W/11NESE

Location ID: 334984

Date: 5/16/2024



Lack of Stabilization – Photo #01251



**Insufficient Vehicle Tracking BMPs at Location Entrance/Exit
– Photo #01252**