

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/21/2024

Submitted Date:

05/21/2024

Document Number:

713300926

**FIELD INSPECTION FORM**Loc ID 323229 Inspector Name: Kester, Michael On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**

ECMC Operator Number: 46290

Name of Operator: KP KAUFFMAN COMPANY INC

Address: 1700 LINCOLN ST STE 4550

City: DENVER State: CO Zip: 80203

**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

9 Number of Comments

0 Number of Corrective Actions

☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

| Contact Name  | Phone        | Email                    | Comment         |
|---------------|--------------|--------------------------|-----------------|
| , KPK         | 303-825-4822 | cogcc@kpk.com            | all inspections |
| Silver, Randy | 720-827-6688 | randy.silver@state.co.us |                 |

**Inspected Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num   | Facility Name            | Insp Status |
|-------------|------|--------|-------------|------------|-----------|--------------------------|-------------|
| 244950      | WELL | PR     | 08/01/2023  | GW         | 123-12745 | ROCKY MOUNTAIN FUEL C-10 | PR          |

**General Comment:**

Follow up inspection

**Location**Overall Good: ☒

|                      |                                      |       |  |
|----------------------|--------------------------------------|-------|--|
| <b>Signs/Marker:</b> |                                      |       |  |
| Type                 | WELLHEAD                             |       |  |
| Comment:             | automation mounted on well head sign |       |  |
| Corrective Action:   |                                      | Date: |  |

|                           |  |  |             |
|---------------------------|--|--|-------------|
| Emergency Contact Number: |  |  |             |
| Comment:                  |  |  |             |
| Corrective Action:        |  |  | Date: _____ |

Overall Good: ☒

|                |      |        |  |  |  |
|----------------|------|--------|--|--|--|
| <b>Spills:</b> |      |        |  |  |  |
| Type           | Area | Volume |  |  |  |

In Containment: No

Comment: \_\_\_\_\_

☐ Multiple Spills and Releases?

|                    |               |       |  |
|--------------------|---------------|-------|--|
| <b>Fencing/:</b>   |               |       |  |
| Type               | PUMP JACK     |       |  |
| Comment:           | safety guards |       |  |
| Corrective Action: |               | Date: |  |

|                           |                 |       |                 |
|---------------------------|-----------------|-------|-----------------|
| <b>Equipment:</b>         |                 |       | corrective date |
| Type: Prime Mover         | # 1             |       |                 |
| Comment:                  | natural gas     |       |                 |
| Corrective Action:        |                 | Date: |                 |
| Type: Bradenhead          | # 1             |       |                 |
| Comment:                  | pipd to surface |       |                 |
| Corrective Action:        |                 | Date: |                 |
| Type: Ancillary equipment | # 3             |       |                 |
| Comment:                  | automation      |       |                 |
| Corrective Action:        |                 | Date: |                 |
| Type: Pump Jack           | # 1             |       |                 |
| Comment:                  |                 |       |                 |
| Corrective Action:        |                 | Date: |                 |

|                    |    |       |  |
|--------------------|----|-------|--|
| <b>Venting:</b>    |    |       |  |
| Yes/No             | NO |       |  |
| Comment:           |    |       |  |
| Corrective Action: |    | Date: |  |

|                 |  |  |
|-----------------|--|--|
| <b>Flaring:</b> |  |  |
| Type            |  |  |
| Comment:        |  |  |

|                    |  |       |  |
|--------------------|--|-------|--|
| Corrective Action: |  | Date: |  |
|--------------------|--|-------|--|

Inspected Facilities

Facility ID: 244950    Type: WELL    API Number: 123-12745    Status: PR    Insp. Status: PR

Producing Well

|                    |                                |       |
|--------------------|--------------------------------|-------|
| Comment:           | PR, casing appeared to be open |       |
| Corrective Action: |                                | Date: |

BradenHead

|                         |                              |                        |     |
|-------------------------|------------------------------|------------------------|-----|
| Date of Last Brhd Test: | 08/04/2023                   | Annual Brhd Completed? | Yes |
| Last Brhd Test Results  | Initial Surf Csg Pressure: 0 | Fluid Type:            |     |
|                         | End Surf Csg Pressure: 0     |                        |     |
| Comment:                |                              |                        |     |
| Corrective Action:      |                              | Date:                  |     |

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

ECMC Comments

| Comment   | User    | Date       |
|---|---------|------------|
| Follow up inspection as per Doc # 699505704, corrective actions appeared to have been addressed | kesterm | 05/21/2024 |

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL   |
|--------------|-------------|---|
| 713300927    | site pic    | <a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6557071">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6557071</a> |