

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

05/20/2024

Submitted Date:

05/21/2024

Document Number:

708903845

**FIELD INSPECTION FORM**

Loc ID 335221 Inspector Name: Smelser, Wayne On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

ECMC Operator Number: 96850  
Name of Operator: TEP ROCKY MOUNTAIN LLC  
Address: 1058 COUNTY ROAD 215  
City: PARACHUTE State: CO Zip: 81635

**Findings:**

15 Number of Comments  
0 Number of Corrective Actions  
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
, TEP		COGCCInspectionReports@terraep.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
210527	WELL	PR	03/12/1981	GW	045-06283	CLOUGH 112	PR
272673	WELL	PR	03/30/2005	GW	045-10127	CLOUGH RWF 512-21	PR
272675	WELL	PR	05/01/2023	GW	045-10126	CLOUGH RWF 412-21	PR
274171	WELL	PR	06/14/2005	GW	045-13341	CLOUGH RWF 612-21	PR

**General Comment:**

[CECMC Inspection Report Summary](#)  
On 05/20/2024 at approximately 13:51 hours, I, Compliance Specialist, Wayne Smelser Conducted an on-site inspection at TEP ROCKY MOUNTAIN LLC CLOUGH 112 pad. Location # 335221 in Garfield County Colorado. Location is within High Priority/Density Habitat areas. Location is approximately 241 yards from a creek/drainage that contributes to the Colorado River. While there, I observed normal production operations.

This is a summary of inspection report.

Remote location/Split pad - Wellheads only, production equipment for these 4 wells is located on the RMV 7-21 pad, location # 323900

Location			
<b>Lease Road:</b>			
Type	Access		
comment:			
Corrective Action			Date:
Overall Good: <input type="checkbox"/>			
<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:			
Corrective Action:			Date:
Type	BATTERY		
Comment:	No tank battery on location		
Corrective Action:			Date:
Emergency Contact Number:			
Comment:	911/970-285-9377		
Corrective Action:			Date: _____
Overall Good: <input type="checkbox"/>			
<b>Spills:</b>			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
<b>Fencing/:</b>			
Type	WELLHEAD		
Comment:	Hog panels		
Corrective Action:			Date:
<b>Equipment:</b>			
Type: Bradenhead	# 4		corrective date
Comment:	No form of pressure monitoring equipment located on bradenheads. All bradenhead valves are accessible.		
Corrective Action:			Date:
Type: Plunger Lift	# 3		
Comment:	CLOUGH 112 well is not on plunger lift The 3 other wells are on plunger lift		
Corrective Action:			Date:
Type: Deadman # & Marked	# 4		
Comment:	Marked		
Corrective Action:			Date:
<b>Venting:</b>			
Yes/No	NO		

Comment:			
Corrective Action:		Date:	

**Flaring:**

Type			
Comment:			
Corrective Action:		Date:	

**Inspected Facilities**

Facility ID: 210527 Type: WELL API Number: 045-06283 Status: PR Insp. Status: PR

**Producing Well**

Comment:	Producing, well is not on plunger lift	
Corrective Action:		Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 272673 Type: WELL API Number: 045-10127 Status: PR Insp. Status: PR

**Producing Well**

Comment:	Producing, well on plunger lift	
Corrective Action:		Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 272675 Type: WELL API Number: 045-10126 Status: PR Insp. Status: PR

**Producing Well**

Comment:	Producing, well on plunger lift	
Corrective Action:		Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 274171 Type: WELL API Number: 045-13341 Status: PR Insp. Status: PR

**Producing Well**

Comment:	Producing, well on plunger lift	
Corrective Action:		Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction						
		Ditches				
		Compaction				Light compaction in some sections
Gravel						Sparse to none in some areas
		Gravel				Sparse to none
		Culverts				

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

**ECMC Comments**

Comment	User	Date
Remote location/Split pad - Wellheads only, production equipment for these 4 wells is located on the RMV 7-21 pad, location # 323900	smelserw	05/21/2024

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
708903846	Inspection 708903845 photo log	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6557357">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6557357</a>
708903847	Inspection 708903845 Stormwater photo log	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6557358">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6557358</a>