

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/22/2024

Submitted Date:

05/22/2024

Document Number:

716200070**FIELD INSPECTION FORM**Loc ID 336084 Inspector Name: Carlile, Craig On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**ECMC Operator Number: 47120Name of Operator: KERR MCGEE OIL & GAS ONSHORE LPAddress: P O BOX 173779City: DENVER State: CO Zip: 80217-**Status Summary:**

- ☐
- THIS IS A FOLLOW UP INSPECTION
-
- ☐
- FOLLOW UP INSPECTION REQUIRED
-
- ☒
- NO FOLLOW UP INSPECTION REQUIRED

Findings:11 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
, Oxy		ECMCInspections@Oxy.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
250685	WELL	PR	10/01/2023	GW	123-18488	CAMP 13-19A	PR
445948	TANK BATTERY	AC	08/20/2008		-	CAMP-63N66W 19NWSW	AO
445950	TANK BATTERY	AC	05/30/2016		-	CAMP-63N66W 19NWSW	AO

General Comment:[Routine wellhead and battery inspection.](#)

LocationOverall Good: ☒

Signs/Marker:			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good: ☒

Spills:				
Type	Area	Volume		

In Containment: No

Comment:

☐ Multiple Spills and Releases?

Fencing/:			
Type	IGNITOR/COMBUSTOR		
Comment:	Barb Wire		
Corrective Action:		Date:	
Type	OTHER		
Comment:	GMR and Pig Station Barb Wire		
Corrective Action:		Date:	
Type	SEPARATOR		
Comment:	Barb Wire		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Pipe panel		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	# 2		

Comment:		Date:	
Corrective Action:		Date:	
Type: Pig Station	# 1		
Comment:		Date:	
Corrective Action:		Date:	
Type: Plunger Lift	# 1		
Comment:		Date:	
Corrective Action:		Date:	
Type: Emission Control Device	# 1		
Comment:		Date:	
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 1		
Comment:		Date:	
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	OTHER	PBV FIBERGLASS		,
Comment:					
Corrective Action:					Date:

Paint

Condition	
Other (Content)	
Other (Capacity)	210 Bbl
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Comment:	Shared with crude oil tank. Flood achors installed.				
Corrective Action:				Date:	
Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	1	300 BBLS	STEEL AST		40.208860,-104.826710
Comment:	Flood anchors installed.				
Corrective Action:					
				Date:	

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficent	Base Sufficent	Adequate	
Comment:					
Corrective Action:					Date:

Wells Served By Facilities Above

AirsID

API Number
123-30716
123-30719
123-18488

API Number	AirsID
------------	--------

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type	Ignitor/Combustor	
Comment:		
Corrective Action:		Date:

Inspected Facilities			
Facility ID: 250685	Type: WELL	API Number: 123-18488	Status: PR Insp. Status: PR
Producing Well			
Comment: PR			
Corrective Action:		Date:	
BradenHead			
Date of Last Brhd Test: 06/19/2023		Annual Brhd Completed? Yes	
Last Brhd Test Results		Initial Surf Csg Pressure: 10	Fluid Type: Water
End Surf Csg Pressure: --			
Comment: Plumbed to surface			
Corrective Action:		Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12			
Facility ID: 445948	Type: TANK	API Number: -	Status: AC Insp. Status: AO
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12			
Facility ID: 445950	Type: TANK	API Number: -	Status: AC Insp. Status: AO
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12			
ECMC Comments			
Comment	User	Date	
Routine wellhead and battery inspection.	carlilec	05/22/2024	
Attached Documents			
You can go to ECMC Images (https://ecmc.state.co.us/weblink/) and search by document number:			
Document Num	Description	URL	
716200071	Photos	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6557881	