

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

05/22/2024

Submitted Date:

05/22/2024

Document Number:

696306334

FIELD INSPECTION FORM

Loc ID: 433098 Inspector Name: PETRIE, ERICA On-Site Inspection: 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Findings:

16 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Operator Information:

ECMC Operator Number: 100322
Name of Operator: NOBLE ENERGY INC
Address: 1099 18TH STREET SUITE 1500
City: DENVER State: CO Zip: 80202

Contact Information:

| Contact Name | Phone | Email | Comment |
|--------------|-------|---|---------|
| | | rbucogccinspectionreports@chevron.onmicrosoft.com | |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|------------------------|-------------|
| 433067 | WELL | PR | 08/01/2020 | OW | 123-37452 | Rohn State LD03-62-1HN | PR |
| 433078 | WELL | PR | 08/01/2020 | OW | 123-37459 | Rohn State LD04-63-1HN | PR |
| 433079 | WELL | PR | 08/01/2020 | OW | 123-37460 | Rohn State LD04-62-1HN | PR |
| 433080 | WELL | PR | 08/01/2020 | OW | 123-37461 | Rohn State LD04-62HN | PR |
| 433095 | WELL | PR | 08/01/2020 | OW | 123-37471 | Rohn State LD03-63-1HN | PR |
| 433096 | WELL | PR | 08/01/2020 | OW | 123-37472 | Rohn State LD09-69HN | PR |
| 433101 | WELL | PR | 08/01/2020 | OW | 123-37475 | Rohn State LD03-62HN | PR |
| 433102 | WELL | PR | 08/01/2020 | OW | 123-37476 | Rohn State LD10-69HN | PR |

General Comment:

This is a Well PAD Inspection ONLY

Location

Overall Good:

| | | | |
|----------------------|------------|-------|--|
| Signs/Marker: | | | |
| Type | CONTAINERS | | |
| Comment: | Adequate | | |
| Corrective Action: | | Date: | |
| Type | WELLHEAD | | |
| Comment: | Adequate | | |
| Corrective Action: | | Date: | |

| | | | |
|---------------------------|--|--|-------------|
| Emergency Contact Number: | | | |
| Comment: | | | |
| Corrective Action: | | | Date: _____ |

Overall Good:

| | | | |
|----------------|------|--------|--|
| Spills: | | | |
| Type | Area | Volume | |

In Containment: No

Comment: _____

Multiple Spills and Releases?

| | | | |
|--------------------|-------------|-------|--|
| Fencing/: | | | |
| Type | WELLHEAD | | |
| Comment: | Panels | | |
| Corrective Action: | | Date: | |
| Type | LOCATION | | |
| Comment: | Barbed Wire | | |
| Corrective Action: | | Date: | |

| | | | |
|---------------------|---------------------------------|-------|-----------------|
| Equipment: | | | corrective date |
| Type: Bradenhead | # 8 | | |
| Comment: | Appear to be plumbed to surface | | |
| Corrective Action: | | Date: | |
| Type: Gas Meter Run | # 8 | | |
| Comment: | Gas Lift Injection Meters | | |
| Corrective Action: | | Date: | |
| Type: Plunger Lift | # 8 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

| | | | |
|--------------------|--|-------|--|
| Venting: | | | |
| Yes/No | | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

| | | | |
|--------------------|--|-------|--|
| Flaring: | | | |
| Type | | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

| Inspected Facilities | | | | | | | | | | |
|--|--------|-------|------|-------------|-----------|---------|-------|---------------|----|--|
| Facility ID: | 433067 | Type: | WELL | API Number: | 123-37452 | Status: | PR | Insp. Status: | PR | |
| Producing Well | | | | | | | | | | |
| Comment: | PR | | | | | | | | | |
| Corrective Action: | | | | | | | Date: | | | |
| The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12 | | | | | | | | | | |
| Facility ID: | 433078 | Type: | WELL | API Number: | 123-37459 | Status: | PR | Insp. Status: | PR | |
| Producing Well | | | | | | | | | | |
| Comment: | PR | | | | | | | | | |
| Corrective Action: | | | | | | | Date: | | | |
| The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12 | | | | | | | | | | |
| Facility ID: | 433079 | Type: | WELL | API Number: | 123-37460 | Status: | PR | Insp. Status: | PR | |
| Producing Well | | | | | | | | | | |
| Comment: | PR | | | | | | | | | |
| Corrective Action: | | | | | | | Date: | | | |
| The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12 | | | | | | | | | | |
| Facility ID: | 433080 | Type: | WELL | API Number: | 123-37461 | Status: | PR | Insp. Status: | PR | |
| Producing Well | | | | | | | | | | |
| Comment: | PR | | | | | | | | | |
| Corrective Action: | | | | | | | Date: | | | |
| The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12 | | | | | | | | | | |
| Facility ID: | 433095 | Type: | WELL | API Number: | 123-37471 | Status: | PR | Insp. Status: | PR | |
| Producing Well | | | | | | | | | | |
| Comment: | PR | | | | | | | | | |
| Corrective Action: | | | | | | | Date: | | | |
| The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12 | | | | | | | | | | |
| Facility ID: | 433096 | Type: | WELL | API Number: | 123-37472 | Status: | PR | Insp. Status: | PR | |
| Producing Well | | | | | | | | | | |
| Comment: | PR | | | | | | | | | |
| Corrective Action: | | | | | | | Date: | | | |
| The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12 | | | | | | | | | | |
| Facility ID: | 433101 | Type: | WELL | API Number: | 123-37475 | Status: | PR | Insp. Status: | PR | |
| Producing Well | | | | | | | | | | |
| Comment: | PR | | | | | | | | | |
| Corrective Action: | | | | | | | Date: | | | |
| The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12 | | | | | | | | | | |
| Facility ID: | 433102 | Type: | WELL | API Number: | 123-37476 | Status: | PR | Insp. Status: | PR | |
| Producing Well | | | | | | | | | | |
| Comment: | PR | | | | | | | | | |
| Corrective Action: | | | | | | | Date: | | | |
| The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12 | | | | | | | | | | |

Producing Well

| | | |
|--------------------|----|-------|
| Comment: | PR | |
| Corrective Action: | | Date: |

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

ECMC Comments

| Comment | User | Date |
|--------------------------|--------|------------|
| Routine Field Inspection | petrie | 05/22/2024 |

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|-------------|---|
| 696306335 | Photos | https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6558094 |