

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/22/2024

Submitted Date:

05/22/2024

Document Number:

696306336

FIELD INSPECTION FORMLoc ID 433076 Inspector Name: PETRIE, ERICA On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

ECMC Operator Number: 100322

Name of Operator: NOBLE ENERGY INC

Address: 1099 18TH STREET SUITE 1500

City: DENVER State: CO Zip: 80202

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:

16 Number of Comments

0 Number of Corrective Actions

☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		rbucogccinspectionreports@c hevron.onmicrosoft.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
433062	WELL	PR	10/01/2023	OW	123-37448	Rohn State LD04-63HN	PR
433066	WELL	PR	08/01/2020	OW	123-37451	Rohn State LD04-65-1HN	PR
433068	WELL	PR	08/01/2020	OW	123-37453	Rohn State LD03-63HN	PR
433075	WELL	PR	08/01/2020	OW	123-37457	Rohn State LD03-64HN	PR
433081	WELL	PR	02/01/2023	OW	123-37462	Rohn State LD03-64-1HN	PR
433083	WELL	PR	08/01/2020	OW	123-37463	Rohn State LD04-64HN	PR
433091	WELL	PR	08/01/2020	OW	123-37467	Rohn State LD03-65-1HN	PR
433109	WELL	PR	08/01/2020	OW	123-37482	Rohn State LD04-64-1HN	PR

General Comment:

This is a Well PAD Inspection ONLY

LocationOverall Good: ☒**Signs/Marker:**

Type	CONTAINERS		
Comment:	Adequate		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Adequate		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good: ☒**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

Type	LOCATION		
Comment:	Barbed Wire		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Panels		
Corrective Action:		Date:	

Equipment:

Type: Bradenhead	# 8		corrective date
Comment:	Appear to be plumbed to surface		
Corrective Action:		Date:	
Type: Plunger Lift	# 8		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 8		
Comment:	Gas Lift Injection Meters		
Corrective Action:		Date:	

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:			
Type			
Comment:			
Corrective Action:		Date:	

--	--	--	--

Inspected Facilities									
Facility ID:	433062	Type:	WELL	API Number:	123-37448	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	PR								
Corrective Action:					Date:				
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									
Facility ID:	433066	Type:	WELL	API Number:	123-37451	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	PR								
Corrective Action:					Date:				
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									
Facility ID:	433068	Type:	WELL	API Number:	123-37453	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	PR								
Corrective Action:					Date:				
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									
Facility ID:	433075	Type:	WELL	API Number:	123-37457	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	PR								
Corrective Action:					Date:				
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									
Facility ID:	433081	Type:	WELL	API Number:	123-37462	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	PR								
Corrective Action:					Date:				
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									
Facility ID:	433083	Type:	WELL	API Number:	123-37463	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	PR								
Corrective Action:					Date:				
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									
Facility ID:	433091	Type:	WELL	API Number:	123-37467	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	PR								
Corrective Action:					Date:				
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									
Facility ID:	433109	Type:	WELL	API Number:	123-37482	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	PR								
Corrective Action:					Date:				
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									

Producing Well			
Comment:	PR		
Corrective Action:		Date:	

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

ECMC Comments		
Comment	User	Date
Routine Field Inspection	petrie	05/22/2024

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
696306340	Photos	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6558095