

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/21/2024

Submitted Date:

05/22/2024

Document Number:

707602834

**FIELD INSPECTION FORM**Loc ID 331337 Inspector Name: Evins, Bret On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**

ECMC Operator Number: 69175

Name of Operator: PDC ENERGY INC

Address: 1099 18TH STREET SUITE 1500

City: DENVER State: CO Zip: 80202

**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

4 Number of Comments

0 Number of Corrective Actions

☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		cogccinspection@pdce.com	All Inspections

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
260616	WELL	PA	02/18/2020	OW	123-20517	WACKER 32-10	PA

**General Comment:**

This is a PLUGGED &amp; ABANDONED WELL / ABANDONED BATTERY inspection.

Well(s): 1: Plugged &amp; Abandoned | PA.

Battery: Abandoned. ALL equipment has been removed.

Abandoned Battery SE corner GPS coordinates: 40.419250 / -104.536110

Abandoned Centralized Battery formerly served 2 Location IDs  
(330540, 331337).

(Well(s): 2: Plugged &amp; Abandoned | PA).

Location

Overall Good: ☐

Emergency Contact Number:

Comment:

Corrective Action:

Date:

Overall Good: ☐

Spills:

Type	Area	Volume		
In Containment: No				
Comment:				
<input type="checkbox"/> Multiple Spills and Releases?				

Equipment:

			corrective date
Type: Plunger Lift	# 0		
Comment: Plugged & Abandoned   PA. Equipment removed.			
Corrective Action:		Date:	

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

**Inspected Facilities**

Facility ID: 260616 Type: WELL API Number: 123-20517 Status: PA Insp. Status: PA

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

**ECMC Comments**

Comment	User	Date
<p><b>CECMC Inspection Report Synopsis:</b></p> <p>On TUE 05/21/2024 at approximately 17:04 hrs. I, Bret Evins, conducted an onsite inspection at: Operator Name: PDC ENERGY INC Location Name: WACKER-65N64W/10SWNE Location ID: 331337 Well Name(s) &amp; API: Reference: See "Inspected Facilities" section on page 1 of this Field Inspection Report. Location County: Weld County, Colorado Weather: Mostly Cloudy, damp from prior storm.</p> <p>While there, I observed: Well(s): 1: Plugged &amp; Abandoned   PA. Battery: Abandoned. ALL equipment has been removed. Abandoned Battery SE corner GPS coordinates: 40.419250 / -104.536110</p> <p><b>WELL STATUS COMMENT:</b> Plugged &amp; Abandoned   PA. Form 6-SRA on file. Plugging, cut/cap date: 02/18/2020. Approved. Plugged &amp; Abandoned   PA well GPS coordinates: 40.416140 / -104.534720</p> <p>Routine inspection.</p> <p>*Any Corrective Actions from prior inspections that have not been addressed remain applicable.</p>	evinsb	05/22/2024

**Attached Documents**You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
707602835	Site photo(s)	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6558451">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6558451</a>