

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

05/21/2024

Submitted Date:

05/22/2024

Document Number:

707602840

**FIELD INSPECTION FORM**

Loc ID 331196 Inspector Name: Evins, Bret On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

ECMC Operator Number: 69175  
Name of Operator: PDC ENERGY INC  
Address: 1099 18TH STREET SUITE 1500  
City: DENVER State: CO Zip: 80202

**Findings:**

4 Number of Comments  
0 Number of Corrective Actions  
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
		cogccinspection@pdce.com	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
259305	WELL	PA	02/12/2020	GW	123-20294	WACKER 10-D	PA

**General Comment:**

This is a **PLUGGED & ABANDONED WELL** inspection.  
Well(s): 1: Plugged & Abandoned | PA.  
Battery: Abandoned. ALL equipment has been removed.  
Abandoned Battery SE corner GPS coordinates: 40.418950 / -104.537270

Abandoned Centralized Battery formerly served 3 Location IDs (326475, 330541, 331196).  
(Well(s): 3: Plugged & Abandoned | PA).

**Location**

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

Overall Good:

**Spills:**

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

**Equipment:**

Type	Area	Volume	corrective date
Plunger Lift	# 0		
Comment:	Plugged & Abandoned   PA. Equipment removed.		
Corrective Action:			Date:

**Venting:**

Yes/No		
Comment:		
Corrective Action:		Date:

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

**Inspected Facilities**

Facility ID: 259305 Type: WELL API Number: 123-20294 Status: PA Insp. Status: PA

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

**ECMC Comments**

Comment	User	Date
<p><b>CECMC Inspection Report Synopsis:</b></p> <p>On TUE 05/21/2024 at approximately 17:26 hrs. I, Bret Evins, conducted an onsite inspection at:                      Operator Name: PDC ENERGY INC                      Location Name: WACKER-65N64W/10NENW                      Location ID: 331196                      Well Name(s) &amp; API:                      Reference:                      See "Inspected Facilities" section on page 1 of this Field Inspection Report.                      Location County: Weld County, Colorado                      Weather: Partly Sunny, damp from prior storm.</p> <p>While there, I observed:                      Well(s): 1: Plugged &amp; Abandoned   PA.                      Battery: Abandoned. ALL equipment has been removed.                      Abandoned Battery SE corner GPS coordinates: 40.418950 / -104.537270</p> <p><b>WELL STATUS COMMENT:</b>                      Plugged &amp; Abandoned   PA.                      Form 6-SRA on file. Plugging, cut/cap date: 02/12/2020. Approved.                      Plugged &amp; Abandoned   PA well GPS coordinates: 40.417390 / -104.541060</p> <p>Routine inspection.</p> <p>*Any Corrective Actions from prior inspections that have not been addressed remain applicable.</p>	evinsb	05/22/2024

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
707602841	Site photo(s)	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6558454">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6558454</a>