

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

05/21/2024

Submitted Date:

05/22/2024

Document Number:

707602842

FIELD INSPECTION FORM

Loc ID 331049 Inspector Name: Evins, Bret On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 69175
 Name of Operator: PDC ENERGY INC
 Address: 1099 18TH STREET SUITE 1500
 City: DENVER State: CO Zip: 80202

Findings:

- 6 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
,		cogccinspection@pdce.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
258104	WELL	PA	11/05/2020	GW	123-20072	MILLAGE 11-10	PA

General Comment:

This is a **PLUGGED & ABANDONED WELL / ABANDONED BATTERY** inspection.
 Well(s): 1: Plugged & Abandoned | PA.
 Battery: Abandoned. ALL equipment has been removed.
 Abandoned Battery SE corner GPS coordinates: 40.420720 / -104.543650

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good:

Spills:					
Type	Area	Volume			

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:			corrective date
Type: Gas Meter Run	# 0		
Comment:	Plugged & Abandoned PA. Battery Abandoned. Equipment removed.		
Corrective Action:			Date:
Type: Plunger Lift	# 0		
Comment:	Plugged & Abandoned PA. Equipment removed.		
Corrective Action:			Date:
Type: Emission Control Device	# 0		
Comment:	Plugged & Abandoned PA. Battery Abandoned. Equipment removed.		
Corrective Action:			Date:

Venting:			
Yes/No			
Comment:			
Corrective Action:			Date:

Flaring:			
Type			
Comment:			
Corrective Action:			Date:

Inspected FacilitiesFacility ID: 258104 Type: WELL API Number: 123-20072 Status: PA Insp. Status: PA

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

ECMC Comments

Comment	User	Date
<p>CECMC Inspection Report Synopsis:</p> <p>On TUE 05/21/2024 at approximately 17:43 hrs. I, Bret Evins, conducted an onsite inspection at: Operator Name: PDC ENERGY INC Location Name: MILLAGE-65N64W/10NWNW Location ID: 331049 Well Name(s) & API: Reference: See "Inspected Facilities" section on page 1 of this Field Inspection Report. Location County: Weld County, Colorado Weather: Partly Sunny, damp from prior storm.</p> <p>While there, I observed: Well(s): 1: Plugged & Abandoned PA. Battery: Abandoned. ALL equipment has been removed. Abandoned Battery SE corner GPS coordinates: 40.420720 / -104.543650</p> <p>WELL STATUS COMMENT: Plugged & Abandoned PA. Form 6-SRA on file. Plugging, cut/cap date: 11/05/2020. Approved. Plugged & Abandoned PA well GPS coordinates: 40.420110 / -104.543640</p> <p>Routine inspection.</p> <p>*Any Corrective Actions from prior inspections that have not been addressed remain applicable.</p>	evinsb	05/22/2024

Attached DocumentsYou can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
707602843	Site photo(s)	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6558455