

Inspection Photos

API: 043-40000

Operator: JAVERNICK OIL

Inspection Date: 5/20/2024



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos



Photo 1. Facing north along the former access road. There is erosion along the road that must be repaired.



Inspection Photos



Photo 3. Facing northeast toward the abandoned wellsite. It appears most of the debris has been removed and reclamation was performed since previous inspection.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

API: 043-40000 | Date: 5/20/2024

Inspection Photos



Photo 3. Facing northwest at the location. There was straw applied to soil but has mostly blown off. Did not observe much germination occurring.



Inspection Photos



Photo 4. Facing north at the wellsite. The abandoned power pole has been removed and the cement blocks.



Inspection Photos



Photo 5. Facing south at the abandoned location.

