

# Inspection Photos

API# 043-40014

Operator: **JAVERNICK OIL**

Inspection Date: 3/20/2024

County: **FREMONT**



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos



**Photo 1.** Drone aerial photo facing northeast. There is a new road built on the left side however the original access road remain unreclaimed in center of the photo.



**COLORADO**  
Energy & Carbon Management  
Commission

Department of Natural Resources

API# 043-40014 | Date: 3/20/2024

## Inspection Photos



**Photo 2.** Drone aerial photo facing northeast. Access road has not been reclaimed.



**COLORADO**  
Energy & Carbon Management  
Commission

Department of Natural Resources

API# 043-40014 | Date: 3/20/2024

## Inspection Photos



**Photo 3.** Drone aerial photo facing northeast toward the location which has not been recontoured and reclaimed..



**COLORADO**  
Energy & Carbon Management  
Commission

Department of Natural Resources

API# 043-40014 | Date: 3/20/2024

## Inspection Photos



**Photo 3.** Drone aerial photo facing north. There was an additional access road that goes to the Drapper 4 wellsite. This road has not been reclaimed.



**COLORADO**  
Energy & Carbon Management  
Commission

Department of Natural Resources

API# 043-40014 | Date: 3/20/2024

## Inspection Photos



**Photo 5.** Facing south along the access road shown in the previous photo. This road is not reclaimed or stabilized.



## Inspection Photos



**Photo 6.** Facing south along the access road. This road is not recontoured.



**COLORADO**  
Energy & Carbon Management  
Commission

Department of Natural Resources

API# 043-40014 | Date: 3/20/2024