

# Construction and Stormwater Inspection

Date: 05/21/2024

Operator: KERR MCGEE OIL & GAS ONSHORE LP -  
47120

Location ID: 485056

Inspection Document #: 708201262

Weld County, CO



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

Inspection Photos  
Location Name: Schmerge 9-4 HZ  
Location ID: 485056



**Photo 1.** Track Out pad installed at the access road entrance.

Inspection Photos  
Location Name: Schmerge 9-4 HZ  
Location ID: 485056



**Photo 2.** Erosion degradation previously documented appears to have been repaired and stormwater control measures/BMPs have been installed.

Inspection Photos  
Location Name: Schmerge 9-4 HZ  
Location ID: 485056



**Photo 3.** See comments in Photo 2.

Inspection Photos  
Location Name: Schmerge 9-4 HZ  
Location ID: 485056



**Photo 4.** See comments in Photo 2.

Inspection Photos  
Location Name: Schmerge 9-4 HZ  
Location ID: 485056



**Photo 5.** Taken from the southeast corner of the topsoil stockpile. Stockpile has been seeded and mulched for long term stabilization. Germination was observed throughout the stockpile at the time of this inspection.

Inspection Photos  
Location Name: Schmerge 9-4 HZ  
Location ID: 485056



**Photo 6.** North side of topsoil stockpile, facing south; see comments in Photo 5.

Inspection Photos  
Location Name: Schmerge 9-4 HZ  
Location ID: 485056



**Photo 7.** North side of topsoil stockpile, facing east; see comments in Photo 5.

Inspection Photos  
Location Name: Schmerge 9-4 HZ  
Location ID: 485056



**Photo 8.** Southside of topsoil stockpile, facing northeast; see comments in Photo 5.

Inspection Photos  
Location Name: Schmerge 9-4 HZ  
Location ID: 485056



**Photo 9.** Taken from the top/upper portion of the topsoil stockpile. Photo illustrates that straw mulch appears to have blown off the top, though, germination was evident. Operator will need to monitor and manage the stockpile to ensure that it is properly protected against wind/water erosion and stabilized for long term until interim reclamation commences.

Inspection Photos  
Location Name: Schmerge 9-4 HZ  
Location ID: 485056



**Photo 10.** Taken from the north/northwest portion of the disturbance area. Perimeter ditch and berm soils appear to have been stabilized with hydromulch.

Inspection Photos  
Location Name: Schmerge 9-4 HZ  
Location ID: 485056



**Photo 11.** Taken from the north/northwest portion of the disturbance area; see comments in Photo 10.

Inspection Photos  
Location Name: Schmerge 9-4 HZ  
Location ID: 485056



**Photo 12.** Armored spillway located on the northwest corner of the drilling pad.

Inspection Photos  
Location Name: Schmerge 9-4 HZ  
Location ID: 485056



**Photo 13.** Erosion degradation (e.g. riling and sediment deposition) observed on the northwest portion of the location. BMPs require maintenance.

Inspection Photos  
Location Name: Schmerge 9-4 HZ  
Location ID: 485056



**Photo 14.** Erosion degradation (e.g. riling and sediment deposition) observed on the northwest portion of the location. BMPs require maintenance.

Inspection Photos  
Location Name: Schmerge 9-4 HZ  
Location ID: 485056



**Photo 15.** Sediment trap requires maintenance.

Inspection Photos  
Location Name: Schmerge 9-4 HZ  
Location ID: 485056



**Photo 16.** Erosion degradation (e.g. riling and sediment deposition) observed on the west portion of the location. BMPs require maintenance.



**Photo 17.** Sediment trap requires maintenance.

Inspection Photos  
Location Name: Schmerge 9-4 HZ  
Location ID: 485056



**Photo 18.** Erosion degradation (e.g. riling and sediment deposition) observed on the west portion of the location. BMPs require maintenance.

Inspection Photos  
Location Name: Schmerge 9-4 HZ  
Location ID: 485056



**Photo 19.** Overview of drilling pad, taken from the southwest corner.

Inspection Photos  
Location Name: Schmerge 9-4 HZ  
Location ID: 485056



**Photo 20.** Taken near the southwest corner of the location. Field Bindweed (CO List C Noxious Weed) was observed growing throughout. This noxious weed will need to be actively managed.

Inspection Photos  
Location Name: Schmerge 9-4 HZ  
Location ID: 485056



**Photo 21.** Taken from the southeast corner of the location. Field Bindweed (CO List C Noxious Weed) was observed growing throughout. This noxious weed will need to be actively managed.